

DEKRA's commission No. : PKOL(W)/LODZ/80738/25/10/21
commission/ damage No. : 23/001377
Date of commission: 21-10-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0135064
Manufacturer	VOLKSWAGEN
Model	T-Roc 17-21
Type / version	T-ROC 1.5 TSI GPF ACT Premium DSG
Body type	hatchback
Number of doors / seats	5/5
Curb weight [kg]	1338
Gross vehicle weight [kg]	1860
Wheelbase 1/2	2590
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	1498
Engine Power [hp/kW]	150/110
Gearbox	automatic
Registration /record No.	WP5612R
VIN / serial number	WVGZZZA1ZKV511404
Date of first registration	13-08-2019
Date of next. tech. test	14-08-2026
Year of manufacture	2019 (year has been verified with the manufacturer's base)
Readout [km]	166 214 (read)
Body color / type of coating	white/UNI

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	GOOD RIDE, SOLMAX 1	215/50 18 92W	4,0 mm
	left	GOOD RIDE, SOLMAX 1	215/50 18 92W	4,0 mm
back	right	GOOD RIDE, SOLMAX 1	215/50 18 92W	5,0 mm
	left	GOOD RIDE, SOLMAX 1	215/50 18 92W	5,0 mm

Standard equipment by Eurotax

- | | |
|--|---|
| 1. Adaptive Cruise Control, Brake Assist | 32. Lane control assistant |
| 2. Antilock-Brake-System (ABS) | 33. Leather gearshifter/switch |
| 3. Antilock-Brake-System (ABS), Brake Assist, ESP (Electronical Stabilizing Program), Other, Traction control | 34. Leather steering wheel, Multi functional steering wheel |
| 4. Armrest (s) front | 35. Light alloy wheels from 17", Wheel bolt locks |
| 5. Armrest (s) front, Extra power outlet | 36. Luggage:other |
| 6. Armrest (s) rear, Rear seat-backs foldable in two separate parts | 37. Mobile Tire System |
| 7. Automatic climate control | 38. On board computer |
| 8. Automatic dimlight activation, Follow me home | 39. Other |
| 9. Automatic headlight elevation control | 40. Other |
| 10. Automatic limited slip differential | 41. Other |
| 11. Bluetooth interface, Bord entertainment: other accessories, CD-player, mp3 Player, Radio, USB in | 42. Other |
| 12. Bluetooth interface, Mobile phone preparation | 43. Other |
| 13. Bumpers: other | 44. Other |
| 14. Child seat fixation | 45. Park Distance Control front, Park Distance Control rear |
| 15. Colored glass | 46. Pedestrian Emergency Brake Assist |
| 16. Cornering Headlights, Fog lamps | 47. Power assisted brakes |
| 17. DAB radio | 48. Power windows front, Power windows rear |
| 18. Door mirror(s) electrically adjustable in general, Door mirrors heated | 49. Pre-Crash System |
| 19. Driver seat height adjustable, Driver seat rotatable, Passenger seat height adjustable, Passenger seat rotatable | 50. Rain sensor |
| 20. Exterior design: other | 51. Rear-view mirror autodimming |
| 21. Extra power outlet | 52. Remote controlled central locking |
| 22. Extra power outlet | 53. Roof railing |
| 23. Extra power outlet | 54. Sport seats front |
| 24. Head airbags front, Head airbags rear | 55. Start/Stop system |
| 25. Hill holder | 56. Storage facilities in general |
| 26. Interior decoration: other | 57. Textile upholstery |
| 27. Interior lights: other accessories | 58. Traction control |
| 28. Interior lights: other accessories | 59. Tyre pressure control (RDC) |
| 29. Interior: other | 60. USB in |
| 30. LED Daytime running lights, LED front dim light | 61. Uni-Lackierung |
| 31. LED rear lights | |

Dealer's equipment (selected items)

1. Automated High-beam assist, Blind spot warning, Brake Assist, Door mirror(s) electrically adjustable in general, Other, Rear Cross Traffic Alert -
 Lusterka boczne składane elektrycznie
 Emergency Assist - asystent hamujący w przypadku zasłabnięcia kierowcy
 System Traffic Jam Assist - asystent jazdy w korku
 System Rear Traffic Alert - asystent wyjazdu z miejsca parkingowego
 Blind Spot system - monitorowanie martwego pola
 System Light Assist - automatyczne światła drogowe
2. Bluetooth interface, Bord entertainment: other accessories, CD-player, iPod Interface, mp3 Player, Navigation system, USB in -
3. Door mirrors electrically foldable -
4. Heated seat driver, Heated seat passenger, Other, Windscreen wash-nozzle heated -
 Kontrolka poziomu płynu spryskiwaczy
 Dysze spryskiwaczy podgrzewane

Fotele przednie - podgrzewane	
5. Interior lights: other accessories, Interior: other, Other, Selectable driveline characteristics, Tinted rear windows	-
Podsufitka w kolorze czarnym	
Nakładki na pedały ze stali nierdzewnej	
Wybór profilu jazdy	
Szyby tylne przyciemniane	
Oświetlenie wnętrza Ambiente czerwone	
6. Keyless go	-
7. Leather gearshifter/switch, Leather steering wheel, Multi functional steering wheel, Steering wheel heated, Steering wheel with gear-switches	-
8. Light Alloy wheels 18'', Wheel bolt locks	-
9. Lumbar adjust driver, Lumbar adjust passenger, Seats: other	-
Fotele przednie z regulacją lędźwiową	
Fotel pasażera - składane oparcie	
10. Other	-
11. Other	-
12. Rear view camera	-
13. Tinted rear windows	-

Base value of the vehicle

Base value of the vehicle by Eurotax (net)	-
--	---

Corrections

First registration

Mileage

Equipment

Tyres

Other

Regularity of service review	-
Braki uszkodzenia, stan	-

Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 11-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.


Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 07-11-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating



No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	150 - 200
4	Front left door	to 150
5	Roof	150 - 200
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	150 - 200
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

page 6/37

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

1

Expert comments - regarding valuation

Informacja wymiana oleju od 1500km. Rysy na samochodzie. Odpryski na szybie czołowej.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.

- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika




Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION




Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa




Photo 30.
Tunel środkowy

A photograph of the interior of a Volkswagen Golf 8, focusing on the driver's side. The steering wheel is black with the VW logo in the center and 'VR6' branding on the lower part. Behind the steering wheel is a large digital instrument cluster displaying a speedometer, tachometer, and gear indicator (P). To the right of the steering wheel is a large infotainment screen showing a navigation map with a red location marker. Below the screen is a control panel with various buttons and two rotary dials for climate control. The interior is finished with dark grey or black materials.

[illegible]

DEKRA Polska Sp. z o.o.
02-673 Warszawa, ul. Konstruktorska 12A
www.dekra.pl

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze




Photo 34.

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Książka serwisowa – ostatni przegląd




Photo 36.

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zdjęcie do protokołu



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Pokrywa komory silnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Wykładzina pokrywy komory silnika - Pęknięcie/rozerwanie 1



Photo 42.

Zderzak - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 43.

Błotnik przedni P - Wgniecenie/odkształcenie 1



Photo 44.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Drzwi przednie P - Wgniecenie/odkształcenie 1



Photo 46.

Listwa drzwi przednich P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1



Photo 48.

Felga aluminiowa tylna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Zderzak tylny - Rysa/odprysk 1



Photo 50.

Dach - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Dach - Wgniecenie/odkształcenie 2



Photo 52.

Dach() - Wgniecenie/odkształcenie 3

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1



Photo 54.

Drzwi przed L - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION




Photo 55.

Drzwi przed L - Inne 1



Photo 56.

Fotel prz. praw. - Inne 1

PHOTOGRAPHIC DOCUMENTATION




Photo 57.

Kanapa tyl. - Inne 1