

DEKRA's commission No. : PKOL(W)/LODZ/98915/26/10/22
commission/ damage No. : 22/018650
Date of commission: 22-10-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
DEKRA Polska - współpraca O/Warszawa
inż. Józef Orłowski
TU - Włocławek

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0133059
Manufacturer	AUDI
Model	A6 Avant [C8] 18-23
Type / version	A6 50 TDI mHEV Quattro Sport Tiptronic
Body type	KOM
Number of doors / seats	5/5
Curb weight [kg]	1975
Gross vehicle weight [kg]	2475
Wheelbase 1/2	2924
Engine type	Automatic ignition
Pollution reduction system	KSC
Engine capacity [ccm]	2967
Engine Power [hp/kW]	286/210
Gearbox	automatic 8- gear
Registration /record No.	GD2E936
VIN / serial number	WAUZZZF24MN048245
Date of first registration	22-02-2021
Date of next. tech. test	10-07-2027
Year of manufacture	2020 (year has been verified with the manufacturer's base)
Readout [km]	114 713 (read)
Body color / type of coating	black/METALIK

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	YOKOHAMA, BLUEARTH WINTER V906 SUV	225/55 18 102V	3,5 mm
	left	YOKOHAMA, BLUEARTH WINTER V906 SUV	225/55 18 102V	3,5 mm
back	right	YOKOHAMA, BLUEARTH WINTER V906 SUV	225/55 18 102V	4,0 mm
	left	YOKOHAMA, BLUEARTH WINTER V906 SUV	225/55 18 102V	4,0 mm

Standard equipment by Eurotax

- | | |
|--|---|
| 1. 3 places rear bench, Rear bench foldable in two separate parts | 31. Light Alloy wheels 18" |
| 2. Additional heating | 32. Lumbar adjust driver electric, Lumbar adjust passenger electric |
| 3. Alarm | 33. Metal finish |
| 4. Armrest (s) front, Storage facilities in general | 34. Mirror: others |
| 5. Automated High-beam assist | 35. Mobile Tire System |
| 6. Bluetooth interface | 36. On board computer |
| 7. Bord communication: other | 37. Other |
| 8. Bord entertainment: other accessories | 38. Other |
| 9. Bumpers: other | 39. Other |
| 10. Child seat fixation | 40. Other |
| 11. Cruise control | 41. Other |
| 12. Door mirror with memory, Door mirrors electrically foldable, Door mirrors heated | 42. Other |
| 13. Door mirror(s) electrically adjustable in general | 43. Park Distance Control rear, Rear view camera |
| 14. Driver seat electrically adjustable, Memory seat, Passenger seat electrically adjustable | 44. Power steering |
| 15. Dualzone automatic climate control | 45. Pre-Crash System |
| 16. Electric tailgate | 46. Pre-Crash System |
| 17. Exterior design: other | 47. Radio |
| 18. Exterior design: other | 48. Rear spoiler |
| 19. Exterior design: other | 49. Rear-view mirror autodimming |
| 20. Floor mat | 50. Remote controlled central locking |
| 21. Head airbags front, Head airbags rear | 51. Roof railing |
| 22. Headrests front | 52. Selectable driveline characteristics |
| 23. Heat reflecting windows | 53. Servotronic |
| 24. Interior decoration: other | 54. Sport seats front |
| 25. Interior: other | 55. Sport suspension |
| 26. LED Daytime running lights | 56. Start/Stop system |
| 27. LED front dim light | 57. Steering wheel manually adjustable |
| 28. LED rear lights | 58. Textile upholstery |
| 29. Lane control assistant | 59. Tyre pressure control (RDC) |
| 30. Leather steering wheel, Multi functional steering wheel, Sports steering wheel | 60. Uni-Lackierung |

Dealer's equipment (selected items)

- | | |
|---|---|
| 1. 4 or more zone automatic climate control | - |
| 2. Bord communication: other | - |
| 3. Child seat fixation, Other | - |
| 4. Distance control | - |
| Tempomat z regulacją i limitem prędkości | |
| Audi lane assist - ostrzeżenie przed niezamierzoną zmianą pasa ruchu | |
| Asystent jazdy w korkach | |
| Asystent omijania przeszkody | |
| Asystent skrótu w lewo | |
| Asystent wydajności | |
| 5. Door mirrors autodimming | - |
| 6. Hands-free system | - |
| 7. Heated seat driver, Heated seat passenger | - |
| 8. Interior lights: other accessories | - |
| 9. Interior: other | - |
| 10. Lane control assistant | - |
| 11. Leather steering wheel, Multi functional steering wheel, Sports steering wheel, Steering wheel heated | - |
| 12. Light Alloy wheels 19" | - |
| 13. Metallic paint | - |

- 14. Other -
- 15. Other -
- 16. Park Distance Control front, Park Distance Control rear -
- 17. Rear view camera -
- 18. Selective catalytic reduction (SCR) -
- 19. Side airbags rear -
- 20. Soundsystem -
- 21. Towbar preparation -
- 22. Windscreenwiper: other -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

Earlier repairs -
stwierdzone braki i uszkodzenia -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 10-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 26-10-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
inż. Józef Orłowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	150 - 500
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	150 - 200
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	150 - 200
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

alarm

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia parkingowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

page 5/41

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Nieprawne przyciski funkcyjne w jednym z kluczyków, grot prawidłowy. Pierwsza rejestracja w kraju 02-12-2021. Informacja trwa inicjowanie systemu nawigacji. Widoczne wady lakiernicze. Odpryski na szybie czołowej. Nietypowe odgłosy podczas hamowania, zalecana weryfikacja układu hamulcowego.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.
Próg lewy (widok od przodu)



Photo 12.
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION




Photo 15.

Tarcza hamulcowa przednia prawa




Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION




Photo 17.

Tarcza hamulcowa tylna lewa




Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Komora silnika

PHOTOGRAPHIC DOCUMENTATION




Photo 21.
Numer identyfikacyjny



Photo 22.
Tabliczka znamionowa

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Zestaw wskaźników - przebieg



Photo 24.

Zestaw wskaźników - serwis

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdz.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa



Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.
Kierownica (na wprost)



Photo 32.
Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Książka serwisowa – dane

**Photo 34.**

Książka serwisowa – ostatni przegląd

PHOTOGRAPHIC DOCUMENTATION



Photo 35.
Dow. Rej. Str. 2




Photo 36.
Instrukcje

PHOTOGRAPHIC DOCUMENTATION




Photo 37.
Zestaw naprawczy koła



Photo 38.
Kluczyki

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Pokrywa komory silnika - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 42.

Pokrywa komory silnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Zderzak - Rysa/odprysk 1



Photo 44.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Drzwi przednie P - Rysa/odprysk 1



Photo 46.

Łotnik tylny P / Ściana boczna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Błotnik tylny P / Ściana boczna P - Rysa/odprysk 2




Photo 48.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Felga aluminiowa tylna P - Rysa/odprysk 1



Photo 50.

Pokrywy bagażnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Zderzak tylny - Rysa/odprysk 1



Photo 52.

Zderzak tylny - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION




Photo 53.

Dach - Wgniecenie/odkształcenie 1



Photo 54.

Dach - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Błotnik tylny L / Ściana boczna L - zdjęcie pogładowe 1



Photo 56.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Felga aluminiowa tylna L - Rysa/odprysk 1



Photo 58.

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Drzwi przed L - Wgniecenie/odkształcenie 1



Photo 60.

Drzwi tylne L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Drzwi tylne L - Wgniecenie/odkształcenie 1



Photo 62.

Klamka drzwi tyl L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Felga Aluminiowa przednia L - Rysa/odprysk 1



Photo 64.

Podłokietnik środkowy przedni - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Fotel prz. lew. - Inne 1



Photo 66.

Fotel prz. praw. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.
Kanapa tyl. - Inne 1



Photo 68.
Wykładzina(y) słupka tylnego L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Wykładzina pokrywy tylnej - Rysa/odprysk 1