

DEKRA's commission No. : PKOL(W)/LODZ/79172/25/10/15
commission/ damage No. : 22/031457
Date of commission: 15-10-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Inż. Cezary Zarębski (NEW)
DEKRA Polska - współpraca O/Warszawa

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0119023
Manufacturer	VOLVO
Model	V40 Cross Country 16-19
Type / version	V40 CC T3 Drive-E Summum aut
Body type	hatchback
Number of doors / seats	5/5
Curb weight [kg]	1494
Gross vehicle weight [kg]	1970
Wheelbase 1/2	2646
Engine type	spark ignition
Pollution reduction system	three-way catalytic converter
Engine capacity [ccm]	1498
Engine Power [hp/kW]	152/112
Gearbox	automatic 6- gear
Registration /record No.	WZ584FN
VIN / serial number	YV1MZ32T0K2183210
Date of first registration	14-03-2019
Date of next. tech. test	03-10-2026
Year of manufacture	2019
Readout [km]	125 275 (read)
Body color / type of coating	black/METALIK

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	PIRELLI, CINTURATO P7	225/45 18 95W	4,0 mm
	left	PIRELLI, CINTURATO P7	225/45 18 95W	3,5 mm
back	right	PIRELLI, CINTURATO P7	225/45 18 95W	3,5 mm
	left	PIRELLI, CINTURATO P7	225/45 18 95W	3,5 mm

Standard equipment by Eurotax

- | | |
|---|---|
| 1. Additional gauges | 26. Leather gearshifter/switch |
| 2. Airbag: other | 27. Leather steering wheel |
| 3. Alarm | 28. Leather upholstery |
| 4. Antilock-Brake-System (ABS) | 29. Light alloy wheels from 17" |
| 5. Armrest (s) front | 30. Lumbar adjust driver |
| 6. Automatic climate control | 31. On board computer |
| 7. Bord climate: other | 32. Other |
| 8. Bord communication: other, CD-player, mp3
Player, On board monitor, Radio,
Soundsystem, USB in | 33. Other |
| 9. Cabin air filter | 34. Other |
| 10. Child seat fixation | 35. Passenger seat height adjustable, Passenger
seat with adjustable inclination |
| 11. Cruise control | 36. Power assisted brakes |
| 12. Distribution of braking force electronically | 37. Power assisted brakes |
| 13. Door mirror(s) electrically adjustable in general | 38. Power windows front, Power windows rear |
| 14. Door mirrors electrically foldable, Exterior
lighting: other | 39. Rain sensor |
| 15. Driver airbag, Head airbags front, Passenger
airbag, Side airbag driver and passenger | 40. Rear seat-backs foldable in two separate parts |
| 16. Driver knee airbag | 41. Rear-view mirror autodimming |
| 17. ESP (Electronical Stabilizing Program),
Traction control | 42. Remote controlled central locking |
| 18. Exterior lighting: other | 43. Start/Stop system |
| 19. Exterior thermometer | 44. Steering wheel manually adjustable |
| 20. Floor mat | 45. Steering wheel with radio operation |
| 21. Interior lights: other accessories | 46. Uni-Lackierung |
| 22. Interior lights: other accessories, Mirror: others | 47. Vehicle immobilizer |
| 23. Interior: other | 48. Whiplash-protection-system |
| 24. LED Daytime running lights | 49. Wood finish |
| 25. LED front dim light | |

Dealer's equipment (selected items)

- | | |
|--|---|
| 1. Blind spot warning | - |
| 2. Cargo net | - |
| 3. Diminished spare wheel | - |
| 4. Driver seat electrically adjustable, Memory seat | - |
| 5. Extra power outlet | - |
| 6. Headlamp wash, Navigation system, Park Distance Control rear, Soundsystem | - |
| Czujnik odległości przy parkowaniu - tył | |
| System nawigacji satelitarnej Sensus | |
| Radio SENSUS CONNECT High Perf. Sound DVD/MP3/WMA, 4x45W, 8 głośn., USB, Bluetooth, LCD 7-cali | |
| 7. Heated seat driver, Heated seat passenger | - |
| 8. Interior: other | - |
| 9. Keyless go | - |
| 10. Light Alloy wheels 18" | - |
| 11. Luggage:other | - |
| 12. Metal finish | - |
| 13. Metallic paint | - |
| 14. Park Distance Control front, Park Distance Control rear | - |
| 15. Rear view camera | - |
| 16. Seats: other | - |
| 17. Selectable driveline characteristics | - |
| 18. Wheels: other | - |
| 19. Windows: other | - |
| 20. Windscreen heating | - |

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

CorrectionsFirst registrationMileageEquipmentTyresOther

State of the vehicle -

Earlier repairs -

Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 11-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 03-11-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Inż. Cezary Zarębski (NEW)

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	150 - 200
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	150 - 200
17	Front right fender	150 - 200

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

-other:

Śruby antykradzieżowe

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle has been conducted. Full-scope test drive was not possible due to the lack of documents authorising to use the vehicle on public roads.

Checking of the correctness and / or construction of identification / serial numbers of the object:

Conducted

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the

page 5/38

assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Informacja o zbliżającym się terminie przeglądu. Rysy na samochodzie. Odpryski na szybie czołowej. Utrudnione otwieranie drzwi prawych tylnych.

Restrictive disclaimer - regarding valuation

Samochód wymaga polerowania oraz miejscowych uzupełnień lakieru.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raporu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika




Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Konsola środkowa



Photo 30.

Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.

Kierownica (na wprost)




Photo 32.


Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Dow. Rej. Str.2 i klucze

**Photo 34.**

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION**Photo 35.**

Książka serwisowa – ostatni przegląd

**Photo 36.**

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zdjęcie do protokołu



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 40.

Spoiler zderzaka przedniego - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zderzak - Rysa/odprysk 1



Photo 42.

Drzwi przednie P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Drzwi przednie P - Wgniecenie/odkształcenie 1



Photo 44.

Drzwi tylne P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Próg P - Rysa/odprysk 1



Photo 46.

Ścianka tylna P / Ścianka boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Felga aluminiowa tylna P - Rysa/odprysk 1



Photo 48.

Szyba tylna - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Zderzak tylny - Rysa/odprysk 1



Photo 50.

Zderzak tylny - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Zderzak tylny cz dolna - Rysa/odprysk 1



Photo 52.

Łotnik tylny L / Ściana boczna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1



Photo 54.

Felga aluminiowa tylna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 55.

Drzwi przed L - Rysa/odprysk 1



Photo 56.

Drzwi przed L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Drzwi tylne L - Rysa/odprysk 1



Photo 58.

Drzwi tylne L - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Próg L - Wgniecenie/odkształcenie 1




Photo 60.

Słupek środkowy L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Felga Aluminiowa przednia L - Rysa/odprysk 1



Photo 62.

Tapicerka drzwi przednich P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Osłona p/słoneczna lewa - Inne 1



Photo 64.

Podsufitka - Inne 1