

DEKRA's commission No. : PKOL(W)/LODZ/76990/25/10/08
commission/ damage No. : 22/K00181
Date of commission: 08-10-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0140037
Manufacturer	SKODA
Model	Kamiq 19-24
Type / version	Kamiq 1.5 TSI Style
Body type	hatchback
Number of doors / seats	5/5
Curb weight [kg]	1241
Gross vehicle weight [kg]	1756
Wheelbase 1/2	2639
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	1498
Engine Power [hp/kW]	150/110
Gearbox	manual 6- gear
Registration /record No.	WZ112FL
VIN / serial number	TMBGK6NW2P3019571
Date of first registration	07-09-2022
Date of next. tech. test	02-09-2027
Year of manufacture	2022 (year has been verified with the manufacturer's base)
Readout [km]	74 066 (read)
Body color / type of coating	grafitowy/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	KORMORAN, UHP ULTRA HIGH PERFORMANCE	205/50 17 93V	4,0 mm
	left	KORMORAN, UHP ULTRA HIGH PERFORMANCE	205/50 17 93V	4,0 mm
back	right	KORMORAN, UHP ULTRA HIGH PERFORMANCE	205/50 17 93V	5,0 mm
	left	KORMORAN, UHP ULTRA HIGH PERFORMANCE	205/50 17 93V	5,0 mm

Standard equipment by Eurotax

- | | |
|---|---|
| 1. Antilock-Brake-System (ABS) | 32. Lane control assistant |
| 2. Armrest (s) front | 33. Leather steering wheel, Multi functional steering wheel |
| 3. Automatic climate control | 34. Light alloy wheels from 17" |
| 4. Bluetooth interface | 35. Limited slip differential in general |
| 5. Bord communication: other | 36. Lumbar adjust driver, Lumbar adjust passenger |
| 6. Bord entertainment: other accessories, On board monitor, USB in | 37. On board computer |
| 7. Bord entertainment: other accessories, Radio preparation | 38. Other |
| 8. Brake Assist, Distance control | 39. Other |
| 9. Cruise control | 40. Other |
| 10. DAB radio | 41. Other |
| 11. Diminished spare wheel | 42. Other |
| 12. Door mirror(s) electrically adjustable in general, Door mirrors heated | 43. Park Distance Control front, Park Distance Control rear |
| 13. Driver airbag, Head airbags front, Passenger airbag, Side airbag driver, Side airbag driver and passenger | 44. Passenger seat height adjustable |
| 14. Driver seat height adjustable | 45. Power assisted brakes |
| 15. ESP (Electronical Stabilizing Program) | 46. Power steering |
| 16. Exterior design: other | 47. Power windows front |
| 17. Exterior design: other | 48. Power windows rear |
| 18. Exterior design: other | 49. Rear seat-backs foldable |
| 19. Exterior design: other | 50. Rear view camera |
| 20. Floor mat | 51. Rear wiper |
| 21. Heated seat driver, Heated seat passenger, Windscreen wash-nozzle heated | 52. Remote controlled central locking |
| 22. Hill holder | 53. Roof railing |
| 23. Interior decoration: other | 54. Storage facilities in general |
| 24. Interior lights: other accessories | 55. Storage facilities in general |
| 25. Interior lights: other accessories | 56. Telematic |
| 26. Interior: other | 57. Tinted rear windows |
| 27. Interior: other | 58. Traction control |
| 28. Interior: other | 59. Tyre pressure control (RDC) |
| 29. Keyless go | 60. Uni-Lackierung |
| 30. LED front dim light | 61. Vehicle immobilizer |
| 31. LED rear lights | |

Dealer's equipment (selected items)

1. Adaptive Cruise Control, Adaptive light, Automatic dimlight activation, Door mirror(s) electrically adjustable in general, Door mirrors autodimming, Door mirrors electrically foldable, Door mirrors heated, LED front dim light, Rain sensor, Rear-view mirror autodimming -
- LIGHT AND RAIN ASSIST z Coming/Leaving Home, Tunnel Light + lusterko wsteczne fotochromatyczne
- Tempomat adaptacyjny do 210 km/h (adaptive cruise control)
- Lusterka boczne składane elektrycznie z funkcją p/oślepieniową
- Lampy przednie Full LED z funkcją adaptacji światła AFS
2. Metallic paint -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

CorrectionsFirst registrationMileageEquipmentTyresOther

Regularity of service review -
Earlier repairs -
Braki, uszkodzenia stan -

Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 10-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 27-10-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	150 - 200
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	150 - 200
16	Right front pillar	150 - 500
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

1

Expert comments - regarding valuation

Rysy na samochodzie. Aktywna kontrolka ciśnienia w kołach. Wymagana wymiana oleju i przegląd od 8200km. W CEPIK informacja o szkodzie istotnej - uszkodzenie elementów układu kierowniczego, uszkodzenie elementów układu nośnego

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.

Przekątna przednia lewa



Photo 2.

Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa




Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION




Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdź.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa




Photo 30.
Tunel środkowy

A detailed view of the driver's side interior of a Volvo XC60. The steering wheel is black with a silver Volvo logo in the center and 'AIRBAG' text below it. Behind the wheel is the instrument cluster with two analog gauges (speedometer and tachometer) and a central digital display showing '18.5', '96.5FM', and '50'. To the right is a large infotainment screen displaying '96.5FM' and various media controls. Below the screen are air vents and a climate control panel with two digital temperature displays set to 22.5°C. The interior features black leather upholstery and silver trim accents.

[illegible]

DEKRA Polska Sp. z o.o.
02-673 Warszawa, ul. Konstruktorska 12A
www.dekra.pl

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze



Photo 34.

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Książka serwisowa – ostatni przegląd



Photo 36.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zdjęcie do protokołu



Photo 38.

Szyba czołowa - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zderzak - Rysa/odprysk 1



Photo 40.

Zderzak - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zderzak - Wgniecenie/odkształcenie 1



Photo 42.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Drzwi przednie P - Rysa/odprysk 1



Photo 44.

Drzwi tylne P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1



Photo 46.

Felga aluminiowa tylna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Zderzak tylny - Rysa/odprysk 1



Photo 48.

Zderzak tylny - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Zderzak tylny cz dolna - Rysa/odprysk 1



Photo 50.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Drzwi przed L - Rysa/odprysk 1



Photo 52.

Drzwi przed L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Drzwi tylne L - Rysa/odprysk 1



Photo 54.

Drzwi tylne L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Felga Aluminiowa przednia L - Rysa/odprysk 1



Photo 56.

Reflektor L - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Fotel prz. lew. - Inne 1