

DEKRA's commission No. : PKOL(W)/LODZ/29850/25/04/25
commission/ damage No. : 24/001255
Date of commission: 25-04-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
mgr inż. Andrzej Szymkowiak
DEKRA Polska - O. Wrocław

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0119466
Manufacturer	MERCEDES-BENZ
Model	GLE Coupe [292] 15-19
Type / version	AMG GLE Coupe 43 4-Matic
Body type	hatchback
Number of doors / seats	5/5
Curb weight [kg]	2305
Gross vehicle weight [kg]	2880
Wheelbase 1/2	2915
Engine type	spark ignition
Supercompression	turbocompressor with intercooler
Pollution reduction system	three-way catalytic converter
Emission standard	EURO 6
Engine capacity [ccm]	2996
Engine Power [hp/kW]	390/287
Gearbox	automatic 9- gear
Registration /record No.	FG3173R
VIN / serial number	WDC2923641A131957
Date of first registration	07-12-2018
Date of next. tech. test	24-04-2026
Year of manufacture	2018 (year has been verified with the manufacturer's base)
Readout [km]	104 551 (read)
Body color / type of coating	white/METALIK

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	Continental, WinterContact TS 850 P	275/45 R21 110V	3,0 mm
	left	Continental, WinterContact TS 850 P	275/45 R21 110V	4,0 mm
back	right	Continental, WinterContact TS 850 P	315/40 R21 115V	3,0 mm

left	Continental, WinterContact TS 850 P	315/40 R21 115V	4,0 mm
------	--	-----------------	--------

Standard equipment by Eurotax

- | | |
|---|--|
| 1. Adaptive light, Automated High-beam assist, Cornering Headlights, LED front dim light | 31. LED Daytime running lights |
| 2. Antilock-Brake-System (ABS) | 32. LED rear lights |
| 3. Armrest (s) front, Storage facilities in general | 33. Leather steering wheel, Multi functional steering wheel, Sports steering wheel |
| 4. Armrest (s) rear | 34. Light Allow wheels over 21'' |
| 5. Artificial leather upholstery | 35. Lumbar adjust driver, Lumbar adjust passenger |
| 6. Automatic Emergency Call | 36. Metal finish |
| 7. Automatic Emergency Call | 37. Other |
| 8. Automatic climate control | 38. Other |
| 9. Bluetooth interface, CD-player, iPod Interface, Radio, USB in | 39. Other |
| 10. Body levelling | 40. Other |
| 11. Bord entertainment: other accessories, Radio preparation | 41. Other |
| 12. Child lock manually | 42. Other |
| 13. Child seat fixation | 43. Power assisted brakes |
| 14. Colored glass | 44. Power windows front, Power windows rear |
| 15. Cruise control | 45. Rain sensor |
| 16. Distance control | 46. Rear seat-backs foldable in two separate parts |
| 17. Door mirror(s) electrically adjustable in general | 47. Rear view camera |
| 18. Door mirrors heated | 48. Remote controlled central locking |
| 19. Driver airbag, Head airbags front, Passenger airbag, Side airbag driver, Side airbag driver and passenger | 49. Selectable driveline characteristics |
| 20. Driver knee airbag | 50. Servotronic |
| 21. Driver seat electrically adjustable, Passenger seat electrically adjustable | 51. Start/Stop system |
| 22. ESP (Electronical Stabilizing Program) | 52. Steering wheel manually adjustable |
| 23. Electric tailgate | 53. Storage facilities in general |
| 24. Electronic controlled suspension | 54. Third braking light |
| 25. Electronic controlled suspension | 55. Traction control |
| 26. Exterior design: other | 56. Traction control |
| 27. Exterior design: other | 57. Tyre pressure control (RDC) |
| 28. Exterior design: other | 58. Uni-Lackierung |
| 29. Floor mat | 59. Vehicle immobilizer |
| 30. Interior: other | |

Dealer's equipment (selected items)

- | | |
|---|---|
| 1. Bord communication: other
Carplay
Android Auto
Apple CarPlay | - |
| 2. Bord communication: other, Other | - |
| 3. Bord entertainment: other accessories, DVD-player, Navigation system, On board monitor | - |
| 4. Bord entertainment: other accessories, Other, Soundsystem | - |
| 5. Diminished spare wheel | - |
| 6. Door mirrors autodimming, Door mirrors electrically foldable, Rear-view mirror autodimming
Lusterko po stronie kierowcy oraz wsteczne automatycznie przyciemniające się
Lusterka boczne składane elektrycznie
Oświetlenie wnętrza Ambient z logo Mercedes | - |
| 7. Exterior design: other | - |
| 8. Glass tilt/slide sunroof electric | - |
| 9. Heat reflecting windows, Light Allow wheels over 21'', Tinted rear windows
Dodatkowo przyciemnione szyby boczne tylne oraz szyba tylna | - |

Felgi aluminiowe 21 AMG, 5-podwójnych z ogumieniem	
Szyby atermiczne, przyciemniane	
10. Heated seat driver, Heated seat passenger, Interior: other, Other, Ventilated front seat	-
Fotele komfortowe, przód (wentylowane i podgrzewane)	
Fotele przednie z funkcją podgrzewania	
Podwójna osłona przeciwsłoneczna	
Podsufitka z mikrofibry Dianamica w kolorze czarnym	
11. Interior: other	-
12. Keyless go	-
13. Lane control assistant	-
Aktywny asystent martwego punktu	
Asystent utrzymania pasa ruchu	
Asystent martwego punktu	
14. Memory seat	-
Fotel pasażera regulowany elektrycznie z funkcją pamięci	
4-stopniowa regulacja odcinka lędźwiowego dla fotela kierowcy i pasażera	
Fotel kierowcy regulowany elektrycznie z pamięcią ustawień	
15. Other	-
16. Park Assistant, Park Distance Control front, Park Distance Control rear, Rear view camera	-
Parktronic z aktywnym asystentem parkowania	
Kamery ułatwiające parkowanie 360 stopni (4 sztuki)	
17. Telematic	-
18. Towbar removable	-
19. Under driving protection	-

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Equipment

Tyres

Other

State of the vehicle	-
Stwierdzone braki, uszkodzenia (szacunkowo)	-
podwyższona grubość powłoki lakierniczej/wcześniejsze naprawy	-


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 05-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 06-05-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
mgr inż. Andrzej Szymkowiak

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [µm]
1	Front cover	150 - 300
2	Left front fender	150 - 300
3	Left front pillar	150 - 200
4	Left front wall	150 - 300
5	Roof	150 - 500
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	150 - 300
9	Left side wall	150 - 300
10	Cover/tailgate	150 - 500
11	Side right wall	150 - 300
12	Rear right door	150 - 300
13	Middle right pillar	to 150
14	Front right door	150 - 300
15	Right side sill	to 150
16	Right front pillar	150 - 200
17	Right front fender	150 - 300

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book of the vehicle was not provided.

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below: pojazd udostępniono w warunkach parkingowych

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

fabryczne

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Niesprawne przyciski funkcyjne w jednym z kluczyków, grot prawidłowy. Odpryski na szybie czołowej. Brak zaślepek w tylnej kanapie.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika




Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION




Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdzielczą

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa



Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.

Kierownica (na wprost)



Photo 32.

Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze



Photo 34.

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Książka serwisowa – ostatni przegląd




Photo 36.

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zdjęcie do protokołu



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zdjęcie do protokołu



Photo 42.

Pokrywa komory silnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Pokrywa komory silnika - Rysa/odprysk 2



Photo 44.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Drzwi przednie P - Rysa/odprysk 1



Photo 46.

Drzwi tylne P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Zderzak tylny - Rysa/odprysk 1



Photo 48.

Drzwi tylne L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Felga Aluminiowa przednia L - Rysa/odprysk 1



Photo 50.

Konsola tunelu śr. - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Fotel prz. lew. - Pęknięcie/rozerwanie 1




Photo 52.

Fotel prz. lew. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Fotel prz. lew. - Inne 2



Photo 54.

Fotel prz. praw. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Kanapa tyl. - Inne 1



Photo 56.

Zaglówek fotela prz. L - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Tapicerka drzwi przednich L - Inne 1



Photo 58.

Tapicerka drzwi przednich P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Tapicerka drzwi tylnych L - Rysa/odprysk 1



Photo 60.

Tapicerka drzwi tylnych P - Rysa/odprysk 1