

DEKRA's commission No. : PKOL(W)/LODZ/19302/25/03/17
commission/ damage No. : Futura
Date of commission: 17-03-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Paweł Szwabowicz
DEKRA Polska - O. Lubin

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0155213
Manufacturer	TOYOTA
Model	Corolla TS Kombi 22-
Type / version	Corolla 2.0 Hybrid Comfort
Body type	KOM
Number of doors / seats	5/5
Curb weight [kg]	1494
Gross vehicle weight [kg]	1955
Wheelbase 1/2	2700
Engine type	spark ignition
Pollution reduction system	GPF
Emission standard	EURO 6
Engine capacity [ccm]	1986
Engine Power [hp/kW]	152/112
Gearbox	automatic 1- gear
Registration /record No.	WJ0224L
VIN / serial number	SB1Z53BE40E100774
Date of first registration	05-08-2022
Date of next. tech. test	05-08-2025
Year of manufacture	2022 (year has been verified with the manufacturer's base)
Readout [km]	50 439 (read)
Body color / type of coating	silver/2-warstwowy metalik

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	BRIDGESTONE, ECOPIA EP150	205/55 16 91V	3,5 mm
	left	BRIDGESTONE, ECOPIA EP150	205/55 16 91V	5,5 mm
back	right	BRIDGESTONE, ECOPIA EP150	205/55 16 91V	5,0 mm

left	BRIDGESTONE, ECOPIA EP150	205/55 16 91V	6,0 mm
------	------------------------------	---------------	--------

Standard equipment by Eurotax

- | | |
|---|--|
| 1. Active Emergency Brake Assist | 43. Interior: other |
| 2. Adaptive Cruise Control | 44. Keyless go |
| 3. Android Auto, Apple CarPlay | 45. LED Daytime running lights |
| 4. Antilock-Brake-System (ABS) | 46. LED front dim light |
| 5. Armrest (s) front | 47. LED rear lights |
| 6. Armrest (s) rear | 48. Lane control assistant |
| 7. Automated High-beam assist | 49. Lane control assistant |
| 8. Automatic Emergency Call | 50. Leather gearshifter/switch |
| 9. Automatic antenna/ window-antenna | 51. Leather steering wheel |
| 10. Automatic climate control | 52. Light Alloy wheels 16" |
| 11. Automatic dimlight activation | 53. Luggage compartment cover |
| 12. Bluetooth interface | 54. Luggage:other |
| 13. Bord climate: other | 55. Mobile Tire System |
| 14. Bord climate: other, Online vehicle apps | 56. Multi functional steering wheel |
| 15. Bord communication: other | 57. Navigation system |
| 16. Bord entertainment: other accessories | 58. On board computer |
| 17. Central locking | 59. On board monitor |
| 18. Central locking, Online vehicle apps | 60. On board monitor, Radio, Touchscreen monitor |
| 19. Child lock manually | 61. Online vehicle apps |
| 20. Child seat fixation | 62. Other |
| 21. Cornering Headlights | 63. Other |
| 22. DAB radio | 64. Other |
| 23. Distribution of braking force electronically | 65. Other |
| 24. Door mirror(s) electrically adjustable in general, Door mirrors heated | 66. Other |
| 25. Driver airbag, Head airbags front, Passenger airbag, Side airbag driver, Side airbag driver and passenger | 67. Passenger seat height adjustable |
| 26. Driver knee airbag | 68. Power assisted brakes |
| 27. Driver seat height adjustable | 69. Power steering |
| 28. ESP (Electronical Stabilizing Program), Traction control | 70. Power windows front, Power windows rear |
| 29. Electric parking brake | 71. Pre-Crash System |
| 30. Exterior design: other | 72. Rear bench foldable in two separate parts |
| 31. Exterior design: other | 73. Rear bench foldable in two separate parts |
| 32. Exterior lighting: other, Online vehicle apps | 74. Rear view camera |
| 33. Extra power outlet | 75. Roof railing |
| 34. Extra power outlet | 76. Steering wheel manually adjustabe |
| 35. Floor mat | 77. Steering wheel with gear-switches |
| 36. Fog lamps | 78. Textile upholstery |
| 37. Hill holder | 79. Traction control |
| 38. Interior decoration: other | 80. Traffic sign recognition |
| 39. Interior lights: other accessories | 81. Tyre pressure control (RDC) |
| 40. Interior lights: other accessories | 82. USB in |
| 41. Interior: other | 83. Vehicle immobilizer |
| 42. Interior: other | 84. Voice control for audiosystem, Voice control for navigation system |

Dealer's equipment (selected items)

1. Door mirrors electrically foldable, Heated seat driver, Heated seat passenger, Keyless Engine start, Lumbar adjust driver electric, Other, Park Distance Control front, Park Distance Control rear, Rain sensor, Rear-view mirror autodimming, Wireless device charging

Lusterko wsteczne elektrochromatyczne (przyciemniające się)

Lusterka boczne składane elektrycznie

Czujnik deszczu

Czujniki odległości przy parkowaniu - przód i tył

Fotel kierowcy z elektryczną regulacją odcinka lędźwiowego
System Inteligentny kluczyk - otwieranie i uruchamianie pojazdu bez użycia kluczyka
Stacja bezprzewodowego ładowania telefonu
Fotele przednie podgrzewane
Układ detekcji przeszkód (ICS)
2. Metalic paint -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Other

State of the vehicle -
Earlier repairs -
Braki i uszkodzenia -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 03-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 25-03-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Paweł Szwabowicz

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	150 - 200
2	Front left fender	to 150
3	Left front pillar	150 - 200
4	Front left door	150 - 300
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	150 - 200
9	Rear left fender	150 - 200
11	Right rear fender	150 - 200
12	Right rear door	150 - 300
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	150 - 200
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book of the vehicle was not provided.

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
Warunki parkingowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the

page 6/38

assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika




Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.
Tabliczka znamionowa



Photo 24.
Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION




Photo 29.
Konsola środkowa



Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION**Photo 31.**


Kierownica (na wprost)

**Photo 32.**


Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Dow. Rej. Str.2 i klucze

**Photo 34.**

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION**Photo 35.**

Książka serwisowa – ostatni przegląd

**Photo 36.**

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 38.

Łotnik przedni P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Drzwi tylne P - Rysa/odprysk 1



Photo 40.

Drzwi tylne P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Próg P - Wgniecenie/odkształcenie 1



Photo 42.

Ścianka tylna P / Ścianka boczna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1



Photo 44.

Felga aluminiowa tylna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 45.

Drzwi przed L - zdjęcie poglądowe 1



Photo 46.

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Drzwi przed L - Rysa/odprysk 2



Photo 48.

Drzwi przed L() - Rysa/odprysk 3

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Drzwi przed L - Inne 1



Photo 50.

Drzwi tylne L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Drzwi tylne L - Rysa/odprysk 2




Photo 52.

Drzwi tylne L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Lusterko zew L - Rysa/odprysk 1



Photo 54.

Próg L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Stupek przedni L - Rysa/odprysk 1



Photo 56.

Błotnik przedni L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Błotnik przedni L - Wgniecenie/odkształcenie 1



Photo 58.

Podłokietnik środkowy przedni - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Fotel prz. lew. - Inne 1




Photo 60.

Fotel prz. lew. - Inne 2

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Wykładzina(y) słupka przedniego L - Rysa/odprysk 1