

DEKRA's commission No. : PKOL(W)/LODZ/80270/26/08/27
commission/ damage No. : 23/014881
Date of commission: 27-08-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
DEKRA Polska - współpraca O/Warszawa
inż. Józef Orłowski
TU - Włocławek

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0136410
Manufacturer	AUDI
Model	Q5 16-20
Type / version	Q5 45 TFSI mHEV Quattro Sport
Body type	KOM
Number of doors / seats	5/5
Curb weight [kg]	1852
Gross vehicle weight [kg]	2400
Wheelbase 1/2	2819
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	1984
Engine Power [hp/kW]	245/180
Gearbox	automatic 7- gear
Registration /record No.	FZ2119T
VIN / serial number	WAUZZZFV3L2056681
Date of first registration	10-03-2020
Date of next. tech. test	10-03-2025
Year of manufacture	2020 (year has been verified with the manufacturer's base)
Readout [km]	149 769 (read)
Body color / type of coating	granatowy/METALIK

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	NANKANG, CROSS SPORT SP-9	235/60 18 107W	4,0 mm
	left	NANKANG, CROSS SPORT SP-9	235/60 18 107W	4,0 mm
back	right	NANKANG, CROSS SPORT SP-9	235/60 18 107W	4,0 mm
	left	NANKANG, CROSS SPORT SP-9	235/60 18 107W	4,0 mm

Standard equipment by Eurotax

- | | |
|---|---|
| 1. Additional gauges, Park Distance Control front, Park Distance Control rear | 24. LED rear lights |
| 2. Airbag: other | 25. Leather steering wheel, Multi functional steering wheel |
| 3. Alarm | 26. Light Alloy wheels 18" |
| 4. Automatic climate control | 27. Metal finish |
| 5. Automatic headlight elevation control, Xenon-light | 28. Mirror: others |
| 6. Bluetooth interface | 29. Mobile Tire System |
| 7. Bord communication: other, USB in | 30. Other |
| 8. Bord entertainment: other accessories | 31. Other |
| 9. Cargo net | 32. Other |
| 10. Child seat fixation | 33. Other, Start/Stop system |
| 11. Cruise control | 34. Pre-Crash System |
| 12. Daytime running lights | 35. Radio |
| 13. Door mirror(s) electrically adjustable in general, Door mirrors heated | 36. Rear bench foldable in two separate parts |
| 14. Driver airbag, Passenger airbag | 37. Rear-view mirror autodimming |
| 15. Driver-information-system, On board computer, On board monitor | 38. Remote controlled central locking |
| 16. Electric parking brake | 39. Roof railing |
| 17. Electric tailgate | 40. Selectable driveline characteristics |
| 18. Exterior design: other | 41. Servotronic |
| 19. Exterior design: other | 42. Side airbag driver and passenger |
| 20. Floor mat | 43. Sport seats front |
| 21. Heat reflecting windows | 44. Textile upholstery |
| 22. Interior lights: other accessories | 45. Tyre pressure control (RDC) |
| 23. Interior: other | 46. Uni-Lackierung |

Dealer's equipment (selected items)

- | | |
|--|---|
| 1. Additional gauges, Blind spot warning, Other, Park Distance Control front, Park Distance Control rear, Rear view camera | - |
| Audi parking system plus - czujniki parkowania plus - przód i tył z wizualizacją na ekranie MMI | |
| Kamera ułatwiająca parkowanie | |
| Audi side assist z Audi pre sense rear - system ostrzegania o pojazdach w martwym polu lusterka | |
| System kontroli ruchu poprzecznego z tyłu | |
| System ostrzegania przy wysiadaniu | |
| Audi pre sense basic - systemy wspomagające bezpieczeństwo w celu zminimalizowania skutków kolizji | |
| 2. Alarm, Electric tailgate | - |
| 3. Bluetooth interface, Bord communication: other, DVD-player, Leather steering wheel, Multi functional steering wheel, Navigation system, On board computer, On board monitor, Radio, Soundsystem, USB in | - |
| System nagłośnienia Audi Sound System | |
| Audi phone box | |
| Kierownica 3-ramienna wielofunkcyjna plus, skórzana | |
| Komputer pokładowy z 7-calowym wyświetlaczem kolorowym | |
| System nawi MMI Navigation plus 8,3cala/10GB/DVD/SD/WLAN/TMC-Pro/USB/Bluetooth/Audi connect | |
| Audi connect - 3 lata | |
| 4. Door mirrors electrically foldable, Heated seat driver, Heated seat passenger, Hill holder, LED front dim light, Other, Trizone automatic climate control | - |
| Przystosowanie do montażu fotelika ISOFIX - na fotelu pasażera | |
| Lusterka boczne składane elektrycznie i ogrzewane | |
| Klimatyzacja automatyczna - 3-strefowa | |
| Asystent podjazdu z funkcją Auto Hold | |
| Lampy przednie LED, statyczne światła skrętne, spryskiwacze reflektorów, lampy tylne LED | |
| Kluczyk komfortowy | |
| Fotele przednie podgrzewane | |

Elektroniczna blokada otwarcia drzwi	
5. Driver seat electrically adjustable	-
6. Full size spare wheel	-
7. Head airbags rear, Side airbag driver and passenger, Side airbags rear	-
8. Head-Up Display	-
9. Headrests front	-
10. Interior decoration: other, Interior: other	-
11. Interior: other	-
12. Lumbar adjust driver electric, Lumbar adjust passenger electric	-
13. Metallic paint	-
14. On board computer, On board monitor	-
15. Other	-
16. Other	-
17. Rear bench	-
18. Roof railing	-
19. Soundsystem	-
20. Tinted rear windows	-

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

Earlier repairs -
stwierdzone braki i uszkodzenia -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 08-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 31-08-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
inż. Józef Orłowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [µm]
1	Front cover	150 - 500
2	Left front fender	150 - 300
3	Left front pillar	150 - 300
4	Left front wall	to 150
5	Roof	150 - 300
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	to 150
9	Left side wall	to 150
10	Cover/tailgate	to 150
11	Side right wall	to 150
12	Rear right door	to 150
13	Middle right pillar	to 150
14	Front right door	150 - 200
15	Right side sill	to 150
16	Right front pillar	150 - 300
17	Right front fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:

Elektroniczna

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below: ograniczenia parkingowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

alarm immobilizer

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Brak zaślepek w tylnej kanapie. Pojazd oklejony folią, pomiar lakieru wykonany na folii elementy: dach, pokrywa przednia, błotnik przedni lewy, słupek przedni lewy/prawy. Odpryski na szybie czołowej. Widoczne wady lakiernicze.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.
Próg lewy (widok od przodu)



Photo 12.
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Zestaw wskaźników - serwis



Photo 26.

Widok przez otwarte drzwi przednie lewe

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Kierownica z lewej strony



Photo 28.

Widok przez otwarte drzwi tylne lewe

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Widok z tylnej kanapy na deskę rozd.



Photo 30.

Konsola środkowa

PHOTOGRAPHIC DOCUMENTATION




Photo 31.
Tunel środkowy



Photo 32.
Kierownica (na wprost)

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dowód rej. Str. 1




Photo 34.

Książka serwisowa - dane

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Książka serwisowa – ostatni przegląd



Photo 36.

Dow. Rej. Str. 2

PHOTOGRAPHIC DOCUMENTATION




Photo 37.
Instrukcje



Photo 38.
Kluczyki

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zdjęcie do protokołu




Photo 42.

Pokrywa komory silnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Spoiler zderzaka przedniego - Rysa/odprysk 1




Photo 44.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Drzwi przednie P - Wgniecenie/odkształcenie 1



Photo 46.

Drzwi tylne P - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Drzwi tylne P - Wgniecenie/odkształcenie 1



Photo 48.

Drzwi tylne P - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION




Photo 49.

Drzwi tylne P - Inne 1



Photo 50.

Lusterko zew P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1



Photo 52.

Felga aluminiowa tylna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Szyba tylna - Rysa/odprysk 1



Photo 54.

Zderzak tylny - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Dach - zdjęcie poglądowe 1




Photo 56.

Dach - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Błotnik tylny L / Ściana boczna L - zdjęcie poglądowe 1



Photo 58.

Błotnik tylny L / Ściana boczna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 59.

Błotnik tylny L / Ściana boczna L - Rysa/odprysk 2



Photo 60.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Drzwi przed L - zdjęcie poglądowe 1




Photo 62.

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Drzwi przed L - Wgniecenie/odkształcenie 1



Photo 64.

Drzwi tylne L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Drzwi tylne L - Wgniecenie/odkształcenie 1



Photo 66.

Drzwi tylne L - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION




Photo 67.

Drzwi tylne L() - Wgniecenie/odkształcenie 3



Photo 68.

Listwa drzwi przednich L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 69.

Listwa drzwi tylnych L - Rysa/odprysk 1



Photo 70.

Słupek przedni L - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION




Photo 71.

Słupek przedni L - Inne 1




Photo 72.

Słupek środkowy L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 73.

Felga Aluminiowa przednia L - Rysa/odprysk 1



Photo 74.

Podłokietnik środkowy przedni - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 75.

Osłona p/słoneczna lewa - Inne 1