

DEKRA's commission No. : PKOL(W)/LODZ/73944/25/09/30
commission/ damage No. : PS22/01044
Date of commission: 30-09-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0128359
Manufacturer	ALFA ROMEO
Model	Stelvio 17-22
Type / version	Stelvio 2.9 V6 Bi-Turbo Quadrifoglio Q4 aut
Body type	hatchback
Number of doors / seats	5/5
Curb weight [kg]	1850
Gross vehicle weight [kg]	2460
Wheelbase 1/2	2818
Engine type	spark ignition
Pollution reduction system	three-way catalytic converter
Engine capacity [ccm]	2891
Engine Power [hp/kW]	510/375
Gearbox	automatic
Registration /record No.	CB274NM
VIN / serial number	ZARPAHEV4N7D43979
Date of first registration	08-04-2022
Date of next. tech. test	08-04-2027
Year of manufacture	2022 (year has been verified with the manufacturer's base)
Readout [km]	182 189 (read)
Body color / type of coating	red/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	MICHELIN, PILOT SPORT 4 SUV	255/40 21 102Y	6,0 mm
	left	MICHELIN, PILOT SPORT 4 SUV	255/40 21 102Y	6,0 mm
back	right	MICHELIN, PILOT SUPER SPORT	285/35 21 105Y	5,5 mm
	left	MICHELIN, PILOT SUPER SPORT	285/35 21 105Y	5,5 mm

Standard equipment by Eurotax

- | | |
|--|---|
| 1. Active Emergency Brake Assist | 45. Interior: other |
| 2. Active body control | 46. Interior: other |
| 3. Adaptive Cruise Control | 47. Keyless entry |
| 4. Additional gauges | 48. LED rear lights |
| 5. Alarm | 49. Lane control assistant |
| 6. Android Auto, Apple CarPlay | 50. Leather finish dashbord |
| 7. Automated High-beam assist | 51. Leather gearshifter/switch, Leather steering wheel |
| 8. Automatic dimlight activation | 52. Leather upholstery |
| 9. Battery with enhanced capacity / 2nd battery | 53. Light Alloy wheels 20" |
| 10. Bi-Xenon Head lamps | 54. Limited slip differential: other |
| 11. Blind spot warning | 55. Luggage:other |
| 12. Bluetooth interface, mp3 Player, Navigation system, On board monitor, Radio, Touchscreen monitor | 56. Mobile Tire System |
| 13. Bord climate: other | 57. On board monitor |
| 14. Bord communication: other | 58. Other |
| 15. Child seat fixation | 59. Other |
| 16. DAB radio, Radio | 60. Other |
| 17. Door mirror(s) electrically adjustable in general | 61. Other |
| 18. Door mirrors autodimming | 62. Other |
| 19. Door mirrors electrically foldable, Door mirrors heated | 63. Paint: other, Uni-Lackierung |
| 20. Driver airbag, Head airbags front, Head airbags rear, Passenger airbag, Side airbag driver and passenger | 64. Park Distance Control front, Park Distance Control rear |
| 21. Driver seat electrically adjustable, Memory seat | 65. Passenger seat electrically adjustable |
| 22. Dualzone automatic climate control | 66. Power windows front, Power windows rear |
| 23. Electric tailgate | 67. Rain sensor |
| 24. Electric tailgate | 68. Rear view camera |
| 25. Electric tailgate hands free | 69. Rear-view mirror autodimming |
| 26. Exterior design: other | 70. Remote controlled central locking |
| 27. Exterior design: other | 71. Seats: other |
| 28. Exterior design: other | 72. Selectable driveline characteristics |
| 29. Exterior design: other | 73. Soundsystem |
| 30. Exterior design: other | 74. Sport seats front |
| 31. Exterior design: other | 75. Start/Stop system |
| 32. Exterior design: other | 76. Steering wheel heated |
| 33. Exterior lighting: other | 77. Steering wheel manually adjustabe |
| 34. Extra power outlet | 78. Steering wheel with gear-switches |
| 35. Extra power outlet | 79. Steering wheel with radio operation |
| 36. Headlamp wash | 80. Storage facilities in general |
| 37. Heated seat driver, Heated seat passenger | 81. Tinted rear windows |
| 38. Hill descent control | 82. Traction control |
| 39. Interior decoration: other | 83. Traction control |
| 40. Interior lights: other accessories | 84. Tyre pressure control (RDC) |
| 41. Interior: other | 85. USB in |
| 42. Interior: other | 86. USB in |
| 43. Interior: other | 87. Windscreen wash-nozzle heated |
| 44. Interior: other | 88. Wireless device charging |

Dealer's equipment (selected items)

1. Active Blind spot system, Driver conditioning monitoring, Lane control assistant, Other, Steering: other, Traffic jam assist, Traffic sign recognition -
 Czujnik martwego pola aktywny
 System utrzymania pasa ruchu

System rozpoznawania znaków drogowych	
System ostrzegający o zmęczeniu kierowcy	
System kontroli prędkości (ISC)	
System asystenta ruchu na autostradzie (HAS)	
System asystenta ruchu w korku (TJA)	
2. Exterior design: other	-
3. Glass tilt/slide sunroof electric	-
4. Light Allow wheels over 21"	-
5. Pearl effect paint	-

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

Current market situation -
Uszkodzenia, stan, podwyższona wartość powłoki lakierowej. -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 10-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 22-10-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	150 - 300
2	Left front fender	150 - 300
3	Left front pillar	to 150
4	Left front wall	150 - 300
5	Roof	to 150
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	150 - 300
9	Left side wall	150 - 300
10	Cover/tailgate	150 - 300
11	Side right wall	150 - 300
12	Rear right door	150 - 300
13	Middle right pillar	to 150
14	Front right door	150 - 300
15	Right side sill	to 150
16	Right front pillar	to 150
17	Right front fender	150 - 300

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:

.

Information concerning the origin of the vehicle

Lack of reliable data.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

fabryczne

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Odpryski na szybie czołowej.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji.”

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.

Bok prawy z tyłu



Photo 6.

Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.
Próg lewy (widok od przodu)



Photo 12.
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdz.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Konsola środkowa



Photo 30.

Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.

Kierownica (na wprost)




Photo 32.


Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Dow. Rej. Str.2 i klucze

**Photo 34.**

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION**Photo 35.**

Książka serwisowa – ostatni przegląd

**Photo 36.**

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.
Zestaw naprawy koła



Photo 38.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION




Photo 41.

Zdjęcie do protokołu



Photo 42.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 44.

Pokrywa komory silnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Szyba czołowa - zdjęcie poglądowe 1




Photo 46.

Szyba czołowa - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Zderzak - Rysa/odprysk 1



Photo 48.

Zderzak - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Zderzak() - Rysa/odprysk 3



Photo 50.

Błotnik przedni P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Felga aluminiowa przednia P - Rysa/odprysk 1



Photo 52.

Drzwi przednie P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Drzwi tylne P - Rysa/odprysk 1



Photo 54.

Próg P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Słupek przedni P - Wgniecenie/odkształcenie 1



Photo 56.

Ścianka tylna P / Ścianka boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Felga aluminiowa tylna P - Rysa/odprysk 1



Photo 58.

Dach - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1




Photo 60.

Próg L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Felga Aluminiowa przednia L - Rysa/odprysk 1



Photo 62.

Fotel prz. lew. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Wykładzina pokrywy tylnej - Rysa/odprysk 1