

DEKRA's commission No. : PKOL(W)/LODZ/55913/26/06/17
commission/ damage No. : PS24/04529
Date of commission: 17-06-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0155859
Manufacturer	MAZDA
Model	CX-60 22-
Type / version	CX-60 3.3 D mHEV Homura AWD aut
Body type	KOM
Number of doors / seats	5/5
Curb weight [kg]	1909
Gross vehicle weight [kg]	2516
Wheelbase 1/2	2870
Engine type	Automatic ignition
Pollution reduction system	KSC
Engine capacity [ccm]	3283
Engine Power [hp/kW]	254/187
Gearbox	automatic
Registration /record No.	NO341CS
VIN / serial number	JMZKH0HE501251959
Date of first registration	21-11-2024
Date of next. tech. test	21-11-2027
Year of manufacture	2024 (year has been verified with the manufacturer's base)
Readout [km]	55 662 (read)
Body color / type of coating	grafitowy/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	TOYO, PROXES SPORT	235/50 20 100W	5,0 mm
	left	TOYO, PROXES SPORT	235/50 20 100W	5,0 mm
back	right	TOYO, PROXES SPORT	235/50 20 100W	5,0 mm
	left	TOYO, PROXES SPORT	235/50 20 100W	5,0 mm

Standard equipment by Eurotax

- | | |
|---|---|
| 1. Adaptive Cruise Control | 44. Lane control assistant, Rear view camera |
| 2. Adaptive light, LED front dim light | 45. Leather finish doorpanels |
| 3. Alarm | 46. Leather gearshifter/switch, Leather steering wheel |
| 4. Android Auto, Apple CarPlay | 47. Leather upholstery |
| 5. Antilock-Brake-System (ABS) | 48. Light Alloy wheels 20" |
| 6. Automated High-beam assist | 49. On board monitor |
| 7. Automatic climate control | 50. Online vehicle apps |
| 8. Bluetooth interface | 51. Other |
| 9. Bord climate: other | 52. Other |
| 10. Bord communication: other | 53. Other |
| 11. Bord entertainment: other accessories | 54. Other |
| 12. Brake Assist | 55. Other |
| 13. Brake Assist | 56. Other |
| 14. Cargo net | 57. Other |
| 15. Cruise control | 58. Park Distance Control front, Park Distance Control rear |
| 16. DAB radio | 59. Radio |
| 17. Distance control | 60. Rain sensor |
| 18. Door mirror with memory | 61. Rear Cross Traffic Alert |
| 19. Door mirror(s) electrically adjustable in general, Door mirrors heated | 62. Rear Cross Traffic Alert |
| 20. Door mirrors electrically foldable | 63. Rear Cross Traffic Alert |
| 21. Driver airbag, Passenger airbag | 64. Rear seat heating |
| 22. Driver knee airbag | 65. Rear seat-backs foldable in two separate parts |
| 23. Driver seat electrically adjustable, Passenger seat electrically adjustable | 66. Rear view camera |
| 24. Exterior design: other | 67. Rear-view mirror autodimming |
| 25. Exterior design: other | 68. Seats: other |
| 26. Exterior lighting: other | 69. Seats: other |
| 27. Exterior lighting: other | 70. Selectable driveline characteristics |
| 28. Floor lighting | 71. Side airbag driver and passenger |
| 29. Floor lighting | 72. Side airbag driver and passenger |
| 30. Full Cabin Spoiler | 73. Soundsystem |
| 31. Head airbags front | 74. Steering wheel electrically adjustable |
| 32. Head-Up Display | 75. Steering wheel heated |
| 33. Headlamp wash | 76. Storage facilities in general |
| 34. Heated seat driver, Heated seat passenger | 77. System kontroli prędkości (ISA) |
| 35. Hill holder | 78. System nawigacji hybrydowej Mazda |
| 36. Interior lights: other accessories | 79. Traffic sign recognition |
| 37. Interior lights: other accessories | 80. Trailer parking assist |
| 38. Interior: other | 81. Tyre pressure control (RDC) |
| 39. Keyless Engine start | 82. USB in |
| 40. Keyless entry, Keyless go | 83. USB in |
| 41. LED Daytime running lights | 84. Uni-Lackierung |
| 42. Lane control assistant | 85. Ventilated front seat |
| 43. Lane control assistant | 86. Windscreenwiper: other |

Base value of the vehicle

Base value of the vehicle by Eurotax (net)

Corrections

First registration

Mileage

Tyres

Other

Current market situation -
Uszkodzenia, stan -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 07-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 06-07-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Left front fender	to 150
3	Left front pillar	to 150
4	Left front wall	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	to 150
9	Left side wall	to 150
10	Cover/tailgate	to 150
11	Side right wall	to 150
12	Rear right door	to 150
13	Middle right pillar	to 150
14	Front right door	to 150
15	Right side sill	to 150
16	Right front pillar	to 150
17	Right front fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

fabryczne

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Odpryski na szybie czołowej.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.

Przekątna przednia lewa



Photo 2.

Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION




Photo 15.

Tarcza hamulcowa przednia prawa




Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa




Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Komora silnika

PHOTOGRAPHIC DOCUMENTATION



Photo 21.

Numer identyfikacyjny




Photo 22.

Tabliczka znamionowa

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Zestaw wskaźników - przebieg



Photo 24.

Zestaw wskaźników - serwis

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdź.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Konsola środkowa



Photo 30.

Tunel środkowy


PHOTOGRAPHIC DOCUMENTATION




Photo 31.
Kierownica (na wprost)



Photo 32.
Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Książka serwisowa – dane

**Photo 34.**

Książka serwisowa – ostatni przegląd

PHOTOGRAPHIC DOCUMENTATION**Photo 35.**

Dowód rej. str. 2

**Photo 36.**

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zestaw naprawczy koła



Photo 38.

Kluczyki

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zdjęcie do protokołu



Photo 42.

Szyba czołowa - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION




Photo 43.

Szyba czołowa - Pęknięcie/rozerwanie 1



Photo 44.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Drzwi przednie P - Wgniecenie/odkształcenie 1



Photo 46.

Drzwi tylne P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 47.

Próg P - Rysa/odprysk 1



Photo 48.

Lampa tylna zew P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Pokrywy bagażnika - Wgniecenie/odkształcenie 1



Photo 50.

Zderzak tylny - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Zderzak tylny - Rysa/odprysk 2



Photo 52.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Drzwi przed L - Rysa/odprysk 1



Photo 54.

Drzwi tylne L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Próg L - Rysa/odprysk 1



Photo 56.

Felga Aluminiowa przednia L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Osłona p/słoneczna lewa - Inne 1



Photo 58.

Osłona p/słoneczna prawa - Inne 1