

DEKRA's commission No. : PKOL(W)/LODZ/02591/25/01/13
 commission/ damage No. : 06321/EO/22
 Date of commission: 13-01-2025

DEKRA Poland - Headquarters
 02-673 Warszawa, ul. Konstruktorska 12A

Client :

 PKO Leasing SA
 Świętokrzyska 36
 00-116 Warszawa

Expert:
Marcin Sosnowski.
 DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0154159
Manufacturer	AUDI
Model	A8 [4N] 21-
Type / version	S8 TFSI mHEV Quattro Tiptr.
Body type	sedan
Number of doors / seats	4/5
Curb weight [kg]	2290
Gross vehicle weight [kg]	2835
Wheelbase 1/2	2998
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	3996
Engine Power [hp/kW]	571/420
Gearbox	automatic
Registration /record No.	ZS957RG
VIN / serial number	WAUZZZF8XNN008631
Date of first registration	07-10-2022
Date of next. tech. test	07-10-2025
Year of manufacture	2022 (year has been verified with the manufacturer's base)
Readout [km]	23 412 (read)
Body color / type of coating	grafit/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	PIRELLI, P ZERO	265/40 20 104Y	4,0 mm
	left	PIRELLI, P ZERO	265/40 20 104Y	4,0 mm
back	right	PIRELLI, P ZERO	265/40 20 104Y	4,0 mm
	left	PIRELLI, P ZERO	265/40 20 104Y	4,0 mm

Standard equipment by Eurotax

- | | |
|---|--|
| 1. 360 view camera | 36. Head airbags front, Head airbags rear, Side airbag driver and passenger, Side airbags rear |
| 2. Active body control | 37. Headlamp wash |
| 3. Additional gauges | 38. Heat reflecting windows |
| 4. Alarm | 39. Interior decoration: other |
| 5. All wheel drive permanent, Limited slip differential: other | 40. Interior decoration: other, Interior: other |
| 6. Antilock-Brake-System (ABS) | 41. Interior: other |
| 7. Armrest (s) front, Storage facilities in general | 42. Interior: other |
| 8. Armrest (s) rear, Interior: other, Seats: other | 43. Keyless go |
| 9. Bluetooth interface | 44. LED Daytime running lights |
| 10. Bluetooth interface, Bord entertainment: other accessories, DAB radio, Hands-free system | 45. LED rear lights |
| 11. Bord communication: other | 46. Leather steering wheel, Multi functional steering wheel, Steering wheel electrically adjustable, Steering wheel with gear-switches |
| 12. Bord communication: other | 47. Leather upholstery |
| 13. Bord communication: other, Soundsystem | 48. Light Alloy wheels 20" |
| 14. Bumpers: other | 49. Lumbar adjust driver, Lumbar adjust passenger |
| 15. Colour stripe in windscreen | 50. Metal finish |
| 16. Comfort driver seat, Comfort passenger seat, Driver seat electrically adjustable, Memory seat, Passenger seat electrically adjustable, Sport seats front | 51. Metal finish |
| 17. Cruise control | 52. Metal finish |
| 18. DVD-player | 53. Mobile Tire System |
| 19. Door lights, Interior lights: other accessories, LED interior lighting | 54. Navigation system |
| 20. Door mirror with memory, Door mirror(s) electrically adjustable in general, Door mirrors autodimming, Door mirrors electrically foldable, Door mirrors heated | 55. Other |
| 21. Driver airbag, Passenger airbag | 56. Other |
| 22. Dualzone automatic climate control | 57. Other |
| 23. Dynamic cornering lights, LED front dim light, Side indicators | 58. Park Assistant, Park Distance Control front, Park Distance Control rear |
| 24. ESP (Electronical Stabilizing Program) | 59. Passive Tyre pressure control |
| 25. Electric tailgate | 60. Pre-Crash System |
| 26. Engine Brake | 61. Remote controlled central locking |
| 27. Engine Brake | 62. Servotronic |
| 28. Exterior design: other | 63. Start/Stop system |
| 29. Exterior design: other | 64. Steering: other |
| 30. Exterior design: other | 65. Sunblind rear side door electric, Sunblind tailgate window electric |
| 31. Exterior design: other | 66. Uni-Lackierung |
| 32. Exterior design: other | 67. Vehicle immobilizer |
| 33. Extra power outlet | 68. Wheel bolt locks |
| 34. Floor mat | 69. Windows: other |
| 35. Free service 4 years or more, more than 60000 km | |

Dealer's equipment (selected items)

1. 360 view camera, Autonomous parking system, Blind spot warning, Distance control, Lane control assistant, Pre-Crash System, Rear Cross Traffic Alert, Rear view camera, Traffic sign recognition -
 Pakiet systemów wspomagających ruchu pozamiejskim
 Pakiet systemów wspomagających parkowanie z asystentem zdalnego parkowania plus

Pakiet systemów wspomagających w ruchu miejskim	
Pakiet systemów wspomagających parkowanie z asystentem zdalnego parkowania plus	
Pakiet systemów wspomagających ruchu pozamiejskim	
2. Digital headlamps	-
3. Diminished spare wheel	-
4. Distance control	-
5. Electric tailgate	-
6. Exterior design: other	-
7. Front seat with massage, Ventilated front seat	-
8. Glass sunroof fixed	-
9. Head-Up Display	-
10. Heated seat driver, Heated seat passenger, Rear seat heating	-
11. Interior decoration: other, Interior: other	-
Konsola środkowa, pokrywa poduszki, górna cz.tablicy rozdzielczej, pas w drzwiach w skórze Feinnappa	
Podłokietniki w drzwiach, pas pod szybami, schowek z pokrywą w skórze Feinnappa	
Dodatkowe aplikacje w podłokietnikach w przednich i tylnych drzwiach w skórze Feinnappa	
12. Leather steering wheel, Multi functional steering wheel, Sports steering wheel,	
Steering wheel heated	-
13. Other	-
14. Pearl effect paint	-
15. Soundsystem	-
16. Tinted rear windows	-
17. Traffic sign recognition	-
18. Tyre pressure control (RDC)	-

Base value of the vehicle

Base value of the vehicle by Eurotax (net)	-
--	---

Corrections

First registration

Mileage

Equipment

Tyres

Other

Braki, uszkodzenia	-
Aktualna sytuacja rynkowa	-


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 01-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 20-01-2025

DEKRA's expert:
Marcin Sosnowski.**Document issued electronically valid without signature.**

Measurement of thickness of the vehicle lacquer coating



No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

1

Expert comments - regarding valuation

Rysy na samochodzie.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.
Przekątna przednia prawa



Photo 4.
Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.
Tył



Photo 8.
Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.
Bok lewy z tyłu



Photo 10.
Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.
Próg lewy (widok od przodu)



Photo 12.
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.
Tarcza hamulcowa tylna lewa



Photo 18.
Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Kołło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa




Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.
Kierownica (na wprost)



Photo 32.
Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION




Photo 33.
Dow. Rej. Str.2 i klucze



Photo 34.
Książka serwisowa – ostatni przegląd

PHOTOGRAPHIC DOCUMENTATION



Photo 35.
Zdjęcie do protokołu



Photo 36.
Szyba czołowa - Rysa/odprysk 1