

DEKRA's commission No. : PKOL(W)/LODZ/70508/25/09/18
commission/ damage No. :
Date of commission: 18-09-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :
Tomasz Kurek
PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:
Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0133212
Manufacturer	BMW
Model	Seria 5 [G30/F90] 16-20
Type / version	518d aut
Body type	sedan
Number of doors / seats	4/5
Curb weight [kg]	1580
Gross vehicle weight [kg]	2260
Wheelbase 1/2	2975
Engine type	Automatic ignition
Pollution reduction system	DPF
Engine capacity [ccm]	1995
Engine Power [hp/kW]	150/110
Gearbox	automatic
Registration /record No.	DW2CY27
VIN / serial number	WBAJF11040BJ25821
Date of first registration	28-02-2019
Date of next. tech. test	28-02-2024
Year of manufacture	2019 (year has been verified with the manufacturer's base)
Readout [km]	84 073 (read)
Body color / type of coating	black/UNI

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	BRIDGESTONE, BLIZZAK LM001	225/55 17 97H	5,5 mm
	left	BRIDGESTONE, BLIZZAK LM001	225/55 17 97H	6,0 mm
back	right	BRIDGESTONE, BLIZZAK LM001	225/55 17 97H	5,0 mm
	left	BRIDGESTONE, BLIZZAK LM001	225/55 17 97H	5,5 mm

Standard equipment by Eurotax

- | | |
|---|---|
| 1. Additional gauges | 32. Light alloy wheels from 17" |
| 2. Additional gauges | 33. Mobile Tire System |
| 3. Alarm | 34. Multi functional steering wheel |
| 4. Antilock-Brake-System (ABS) | 35. Navigation system |
| 5. Armrest (s) front | 36. On board computer |
| 6. Armrest (s) rear | 37. Other |
| 7. Automatic dimlight activation, Rain sensor | 38. Other |
| 8. Bluetooth interface, Hands-free system | 39. Other |
| 9. Bord communication: other | 40. Other |
| 10. Bord entertainment: other accessories | 41. Other |
| 11. Brake Assist | 42. Other |
| 12. CD-player | 43. Other |
| 13. Child lock electric | 44. Other |
| 14. Child seat fixation | 45. Park Distance Control front, Park Distance Control rear |
| 15. Collision Warning System | 46. Rear seat-backs foldable in two separate parts |
| 16. Cruise control | 47. Rear-view mirror autodimming |
| 17. Driver airbag, Head airbags front, Passenger airbag, Side airbag driver and passenger | 48. Selectable driveline characteristics |
| 18. Driver seat electrically adjustable, Passenger seat electrically adjustable | 49. Servotronic |
| 19. ESP (Electronical Stabilizing Program), Traction control | 50. Soundsystem |
| 20. Energy recovery system | 51. Start/Stop system |
| 21. Exterior design: other | 52. Start/Stop system |
| 22. Exterior design: other | 53. Steering wheel manually adjustable |
| 23. Exterior design: other | 54. Telematic |
| 24. Exterior lighting: other | 55. Telematic |
| 25. Floor mat | 56. Textile upholstery |
| 26. Follow me home | 57. Tie-down ring |
| 27. Follow me home | 58. Tyre pressure control (RDC) |
| 28. Free service 4 years or more, more than 60000 km | 59. Uni-Lackierung |
| 29. Headlamp wash, LED front dim light | 60. Wheel bolt locks |
| 30. Interior decoration: other | 61. Windscreen wash-nozzle heated |
| 31. Interior: other | |

Dealer's equipment (selected items)

1. Park Assistant -
 Kamera cofania
 Asystent parkowania

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

CorrectionsFirst registration

Equipment

Tyres

Other

Uszkodzenia, braki, stan, weryfikacja serwisowa -

Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 10-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.


Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 09-10-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating



No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

page 5/38

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

1

Expert comments - regarding valuation

Brak aktualnych badań technicznych. Rysy na samochodzie. Aktywna kontrolka silnika. Minął termin wymiany płynu hamulcowego, oleju silnikowego i przeglądu. Informacja o ograniczonym wspomaganie kierownicy. Długotrwały postój samochodu.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznym, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.

- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 5.

Bok prawy z przodu



Photo 6.

Bok prawy z tyłu

PHOTOGRAPHIC DOCUMENTATION



Photo 7.
Przekątna tylna prawa



Photo 8.
Tył

PHOTOGRAPHIC DOCUMENTATION



Photo 9.
Przekątna tylna lewa



Photo 10.
Bok lewy z tyłu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Bok lewy z przodu



Photo 12.

Próg lewy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION




Photo 13.

Numer identyfikacyjny



Photo 14.

Tabliczka znamionowa

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Zestaw wskaźników - przebieg



Photo 16.

Widok przez otwarte drzwi przednie lewe

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Widok przez otwarte drzwi tylne lewe



Photo 18.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Konsola środkowa



Photo 20.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Kierownica (na wprost)



Photo 22.
Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 23.
Komora silnika



Photo 24.
Bagażnik

PHOTOGRAPHIC DOCUMENTATION



Photo 25.
Koło zapasowe



Photo 26.
Spód pojazdu przód

PHOTOGRAPHIC DOCUMENTATION



Photo 27.
Spód pojazdu tył



Photo 28.
Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Tarcza hamulcowa przednia prawa



Photo 30.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION**Photo 31.**

Tarcza hamulcowa tylna lewa

**Photo 32.**

Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze



Photo 34.

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Książka serwisowa – ostatni przegląd



Photo 36.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zdjęcie do protokołu



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 40.

Szyba czołowa - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Szyba czołowa - Pęknięcie/rozerwanie 1



Photo 42.

Wykładzina pokrywy komory silnika - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Zderzak - Rysa/odprysk 1



Photo 44.

Zderzak - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Drzwi przednie P - Wgniecenie/odkształcenie 1



Photo 46.

Drzwi tylne P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Lusterko zew P - Rysa/odprysk 1



Photo 48.

Próg P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Błotnik tylny P / Ściana boczna P - Rysa/odprysk 1



Photo 50.

Zderzak tylny - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Zderzak tylny - Inne 1



Photo 52.

Ścianka tylna L / Ścianka boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 2



Photo 54.

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Drzwi tylne L - Wgniecenie/odkształcenie 1



Photo 56.

Próg L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.
Próg L - Rysa/odprysk 2



Photo 58.
Fotel prz. lew. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Fotel prz. praw. - Inne 1



Photo 60.

Kanapa tyl. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Wykładzina(y) słupka przedniego L - Inne 1



Photo 62.

Listwy progowe praw. - Inne 1