

DEKRA's commission No. : PKOL(W)/LODZ/49317/24/06/27
commission/ damage No. : 22/022627
Date of commission: 27-06-2024

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing Finance
PKO Leasing SA
Al. Śmigłego-Rydza 20
93-281 Łódź

Expert:

Marcin Sosnowski.
DEKRA Polska - Centrala
inż. Józef Orłowski
TU - Włocławek

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0137933
Manufacturer	BMW
Model	Seria 3 [G20] 18-22
Type / version	330e aut
Body type	sedan
Number of doors / seats	4/5
Curb weight [kg]	1770
Gross vehicle weight [kg]	2265
Wheelbase 1/2	2851
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	1998
Engine Power [hp/kW]	184/135
Gearbox	automatic 8- gear
Registration /record No.	DW1SY75
VIN / serial number	WBA5P51050FM78888
Date of first registration	14-07-2022
Date of next. tech. test	14-07-2025
Year of manufacture	2022 (year has been verified with the manufacturer's base)
Readout [km]	40 773 (read)
Body color / type of coating	white/UNI

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	BRIDGESTONE, TURANZA	225/50 17 98Y	5,5 mm
	left	BRIDGESTONE, TURANZA	225/50 17 98Y	5,5 mm
back	right	BRIDGESTONE, TURANZA	225/50 17 98Y	4,5 mm
	left	BRIDGESTONE, TURANZA	225/50 17 98Y	4,5 mm

Standard equipment by Eurotax

1. Active speed sign recognition, Traffic sign recognition
2. Additional gauges
3. Additional gauges
4. Additional gauges, Digital instruments, Navigation system, On board monitor, Touchscreen monitor
5. Airbag: other
6. Android Auto, Apple CarPlay
7. Antilock-Brake-System (ABS)
8. Automatic climate control
9. Bateria wysokiego napięcia
10. Bluetooth interface, Hands-free system, USB in
11. Bord communication: other
12. Bord communication: other
13. Bord communication: other
14. Bord communication: other
15. Bord communication: other
16. Bord entertainment: other accessories
17. Child seat fixation
18. Collision Warning System, Lane control assistant
19. Collision Warning System, Pedestrian Emergency Brake Assist
20. Cruise control
21. Czujnik kolizji
22. Czujnik poziomu i klasy oleju
23. DAB radio
24. Door mirror(s) electrically adjustable in general, Door mirrors heated
25. Driver airbag, Passenger airbag, Side airbag driver and passenger
26. Dysze spryskiwaczy
27. Dywaniki podłogowe welurowe
28. ESP (Electronical Stabilizing Program), Traction control
29. Exterior design: other
30. Exterior design: other
31. Exterior design: other
32. Exterior design: other
33. Exterior design: other, Mirror: others
34. Exterior lighting: other
35. Exterior lighting: other
36. Extra power outlet
37. Filtr cząstek stałych
38. Follow me home
39. Follow me home
40. Fotele przednie standardowe
41. Gniazda USB (1x obszar konsoli środkowej, 1x w obszarze środkowego podłokietnika)
52. Lane control assistant
53. Leather steering wheel, Sports steering wheel
54. Light alloy wheels from 17"
55. Limited slip differential in general
56. Listwy dachowe w kolorze czarnym
57. Mobile Tire System
58. Oczka do mocowania
59. Opcje przechowywania
60. Ostrzeżenie o włączonym świetle
61. Osłona chłodnicy w kształcie nerki, czarna błyszcząca z ramką w perłowym chromie, wysoki połysk
62. Osłony przeciwsłoneczne
63. Other
64. Other
65. Other
66. Other
67. Other
68. Other
69. Other
70. Other
71. Oświetlenie przestrzeni bagażowej
72. Poduszki powietrzne boczne dla kierowcy i pasażera
73. Poduszki powietrzne chroniące głowy osób siedzących z przodu i z tyłu
74. Podłokietnik przedni
75. Podłokietnik tylny centralny
76. Power windows front, Power windows rear
77. Przełącznik zamka centralnego
78. Rain sensor
79. Rear seat-backs foldable in two separate parts
80. Selectable driveline characteristics
81. Selectable driveline characteristics
82. Servotronic
83. Side Pre-Crash System
84. Skrzynia biegów automatyczna Steptronic, 8-biegowa
85. Start/Stop system
86. Steering wheel manually adjustable
87. System alarmowy (monitoring, czujnik ruchu wewnątrz i przechylu, syrena z zasilaniem awaryjnym)
88. System monitorowania ciśnienia w oponach elektroniczny
89. System zamykania z centralnym zamkiem
90. Szyby atermiczne
91. Telematic
92. Telematic

- | | |
|--|------------------------------------|
| 42. Gwarancja na baterię wysokiego napięcia - 6 lat z limitem 100.000 km | 93. Textile upholstery |
| 43. Gwarancja na pojazd bez limitu kilometrów - 2 lata | 94. Traction control |
| 44. Interior decoration: other | 95. Uchwyty na napoje |
| 45. Interior lights: other accessories | 96. Uni-Lackierung |
| 46. Interior lights: other accessories, Storage facilities in general | 97. Vehicle charging cable |
| 47. Keyless Engine start, Keyless go | 98. Vehicle charging cable |
| 48. Kierownica wielofunkcyjna | 99. Vehicle immobilizer |
| 49. Klakson dwutonowy | 100. Wheel bolt locks |
| 50. Klapka ładowania | 101. Zacisk akumulatora bezpieczny |
| 51. LED front dim light, LED rear lights | |

Dealer's equipment (selected items)

- | | |
|---|---|
| 1. Artificial leather upholstery | - |
| 2. Dach szklany, elektrycznie sterowany, zintegrowana owiewka | - |
| 3. Digital key, Keyless entry, Keyless go | - |
| 4. Fotele przednie regulowane elektrycznie, pamięć fotela kierowcy i lusterek, fun. parkingowa lusterek | - |
| 5. Heated seat driver, Heated seat passenger | - |
| 6. Interior decoration: other | - |
| 7. Park Distance Control front, Park Distance Control rear | - |
| 8. Sport seats front | - |

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment


Tyres

Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 07-2024 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 05-07-2024

DEKRA's expert:
Marcin Sosnowski.
inż. Józef Orłowski**Document issued electronically valid without signature.**

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	150 - 300
2	Front left fender	150 - 300
3	Left front pillar	150 - 300
4	Front left door	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	150 - 300
17	Front right fender	150 - 300

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia parkingowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Pojazd częściowo oklejony folią bezbarwną. Szyby boczne przednie przyciemnione folią.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION




Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION




Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa



Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION

Photo 31.
Kierownica (na wprost)



Photo 32.
Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze




Photo 34.

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Książka serwisowa – ostatni przegląd




Photo 36.

Przewód ładowania baterii trakcyjnej

PHOTOGRAPHIC DOCUMENTATION



Photo 37.
Zdjęcie do protokołu



Photo 38.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Szyba czołowa - Rysa/odprysk 1



Photo 40.

Zderzak - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zderzak tylny - Rysa/odprysk 1



Photo 42.

Drzwi tylne L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Błotnik przedni L - Rysa/odprysk 1