

DEKRA's commission No. : PKOL(W)/LODZ/24306/25/04/02
commission/ damage No. : 22/014581
Date of commission: 02-04-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0120036
Manufacturer	AUDI
Model	Q7 15-19
Type / version	SQ7 4.0 TDI Quattro Tiptr.
Body type	KOM
Number of doors / seats	5/7
Curb weight [kg]	2330
Gross vehicle weight [kg]	3200
Wheelbase 1/2	2996
Engine type	Automatic ignition
Pollution reduction system	KSC
Engine capacity [ccm]	3956
Engine Power [hp/kW]	435/320
Gearbox	automatic
Registration /record No.	WZ621EY
VIN / serial number	WAUZZZ4M8HD039211
Date of first registration	07-04-2017
Date of next. tech. test	29-04-2025
Year of manufacture	2017 (year has been verified with the manufacturer's base)
Readout [km]	290 754 (read)
Body color / type of coating	brązowy/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	MICHELIN, PILOT ALPIN 5 SUV	285/40 21 109V	6,0 mm
	left	MICHELIN, PILOT ALPIN 5 SUV	285/40 21 109V	6,0 mm
back	right	MICHELIN, PILOT ALPIN 5 SUV	285/40 21 109V	6,0 mm
	left	MICHELIN, PILOT ALPIN 5 SUV	285/40 21 109V	6,0 mm

Standard equipment by Eurotax

- | | |
|--|---|
| 1. Air suspension, Electronic controlled suspension | 36. LED front dim light |
| 2. Alarm | 37. LED rear lights |
| 3. Alcantara upholstery, Upholstery with leather inserts | 38. Leather steering wheel, Multi functional steering wheel, Sports steering wheel, Steering wheel with gear-switches |
| 4. Antilock-Brake-System (ABS) | 39. Leather steering wheel, Multi functional steering wheel, Steering wheel with gear-switches |
| 5. Armrest (s) front | 40. Light Alloy wheels 20" |
| 6. Automated High-beam assist | 41. Lumbar adjust driver electric, Lumbar adjust passenger electric |
| 7. Automatic climate control | 42. Metal finish |
| 8. Automatic dimlight activation, Rain sensor | 43. Other |
| 9. Bluetooth interface | 44. Other |
| 10. Bluetooth interface, Bord communication: other, Bord entertainment: other accessories, Driver-information-system, Navigation system, On board monitor, Radio | 45. Other |
| 11. Body-coloured bumpers | 46. Other |
| 12. Bord communication: other | 47. Other |
| 13. Bord communication: other | 48. Other |
| 14. Cargo net | 49. Other, Start/Stop system |
| 15. Child lock electric | 50. Park Distance Control rear |
| 16. Child seat fixation | 51. Power windows front, Power windows rear |
| 17. Child seat fixation | 52. Pre-Crash System |
| 18. Cruise control | 53. Pre-Crash System |
| 19. Diminished spare wheel | 54. Rear bench foldable in two separate parts |
| 20. Driver airbag, Head airbags front, Head airbags rear, Passenger airbag, Side airbag driver and passenger | 55. Rear-view mirror autodimming |
| 21. Driver seat electrically adjustable, Lumbar adjust driver electric, Lumbar adjust passenger electric, Passenger seat electrically adjustable | 56. Remote controlled central locking |
| 22. Driver seat height adjustable, Passenger seat height adjustable | 57. Roof railing |
| 23. Driver-information-system, On board computer, On board monitor | 58. Selectable driveline characteristics |
| 24. ESP (Electronical Stabilizing Program) | 59. Servotronic |
| 25. Electric tailgate | 60. Side indicators |
| 26. Exterior design: other | 61. Soundsystem |
| 27. Exterior design: other | 62. Sport seats front |
| 28. Exterior design: other | 63. Steering wheel manually adjustable |
| 29. Exterior design: other | 64. Storage facilities in general |
| 30. Exterior lighting: other, Interior lights: other accessories | 65. Textile upholstery |
| 31. Floor mat | 66. Tyre pressure control (RDC) |
| 32. Headlamp wash | 67. Tyre pressure control (RDC) |
| 33. Heat reflecting windows | 68. Uni-Lackierung |
| 34. Heated seat driver, Heated seat passenger | 69. Vehicle immobilizer |
| 35. Interior: other | |

Dealer's equipment (selected items)

- | | |
|---|---|
| 1. 2 single seats rear, Armrest (s) rear, Child seat fixation | - |
| 2. 4 or more zone automatic climate control | - |
| 3. Additional gauges, Park Distance Control front, Park Distance Control rear | - |
| 4. Door mirror with memory, Door mirrors electrically foldable | - |

5. Driver seat electrically adjustable, Lumbar adjust driver electric, Lumbar adjust passenger electric, Memory seat, Passenger seat electrically adjustable	-
Elektryczna regulacja lędźwiowa foteli przednich	
Fotele przednie regulowane elektrycznie z pamięcią ust. fotela kierowcy	
6. Front seat with massage, Ventilated front seat	-
Fotele z przodu z funkcją wentylacji	
Fotele z przodu z funkcją masażu	
7. Glass sunroof fixed	-
8. Leather steering wheel, Multi functional steering wheel, Sports steering wheel, Steering wheel with gear-switches	-
9. Leather upholstery	-
10. Metallic paint	-
11. Mobile Tire System	-
12. On board computer, On board monitor	-
13. Other	-
14. Rear view camera	-
15. Soundsystem	-
16. Tinted rear windows	-
17. Towbar removable	-

Additional equipment

1. Felgi aluminiowe 21" z ogumieniem	-
--	---

Base value of the vehicle

Base value of the vehicle by Eurotax (gross)	-
--	---

Corrections

First registration

Mileage

Equipment

Tyres

Other

Braki, uszkodzenia stan, weryfikacja serwisowa	-
--	---


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 04-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 07-04-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Left front fender	to 150
3	Left front pillar	to 150
4	Left front wall	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	to 150
9	Left side wall	to 150
10	Cover/tailgate	to 150
11	Side right wall	to 150
12	Rear right door	to 150
13	Middle right pillar	to 150
14	Front right door	to 150
15	Right side sill	to 150
16	Right front pillar	to 150
17	Right front fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

fabryczne

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

1

Expert comments - regarding valuation

Rysy na samochodzie. Aktywna kontrolka silnika. Odpryski na szybie czołowej. Mocowania podłogi bagażnika nie blokuje się do weryfikacji serwisowej.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.

Przekątna przednia lewa



Photo 2.

Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.

Bok prawy z tyłu



Photo 6.

Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód




Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION




Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Konsola środkowa



Photo 30.

Tunel środkowy

A detailed view of the front interior of an Audi A8 L. The steering wheel is made of dark leather with silver-colored Audi rings in the center and silver trim on the lower spokes. Behind the wheel is a large, high-resolution digital instrument cluster displaying various vehicle metrics and a navigation map. To the right of the steering wheel, a large rectangular infotainment screen shows a detailed navigation map. The dashboard and center console are finished with light-colored wood grain. The overall design is minimalist and luxurious, with a focus on high-quality materials and advanced technology.

[illegible]

DEKRA Polska Sp. z o.o.
02-673 Warszawa, ul. Konstruktorska 12A
www.dekra.pl

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze



Photo 34.

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Książka serwisowa – ostatni przegląd



Photo 36.

Zestaw naprawczy koła

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zdjęcie do protokołu



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.
Zdjęcie do protokołu



Photo 40.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 42.

Pokrywa komory silnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Szyba czołowa - zdjęcie pogładowe 1



Photo 44.

Szyba czołowa - zdjęcie pogładowe 2

PHOTOGRAPHIC DOCUMENTATION




Photo 45.

Szyba czołowa - Pęknięcie/rozerwanie 1




Photo 46.

Szyba czołowa - Pęknięcie/rozerwanie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Uszczelka/listwa szyby czołowej - Rysa/odprysk 1



Photo 48.

Uszczelka/listwa szyby czołowej - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Zaślepka prz haka hol. - Rysa/odprysk 1



Photo 50.

Zderzak - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Zderzak - Rysa/odprysk 2



Photo 52.

Zderzak() - Rysa/odprysk 3

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Felga aluminiowa przednia P - Rysa/odprysk 1



Photo 54.

Drzwi przednie P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Drzwi tylne P - Wgniecenie/odkształcenie 1



Photo 56.

Listwa drzwi przednich P - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Listwa drzwi tylnych P - Rysa/odprysk 1



Photo 58.

Listwa drzwi tylnych P - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Próg P - Rysa/odprysk 1



Photo 60.

Próg P - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Stupek przedni P - Rysa/odprysk 1



Photo 62.

Zderzak tylny - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Zderzak tylny - Rysa/odprysk 2



Photo 64.

Błotnik tylny L / Ściana boczna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Felga aluminiowa tylna L - Rysa/odprysk 1



Photo 66.

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Drzwi tylne L - Rysa/odprysk 1



Photo 68.

Listwa drzwi przednich L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Listwa drzwi przednich L - Inne 1



Photo 70.

Listwa drzwi tylnych L - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 71.

Lusterko zew L - Rysa/odprysk 1



Photo 72.

Próg L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 73.

Felga Aluminiowa przednia L - Rysa/odprysk 1



Photo 74.

Konsola tunelu śr. - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 75.

Fotel prz. lew. - Wgniecenie/odkształcenie 1



Photo 76.

Fotel prz. lew. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 77.

Fotel prz. praw. - Wgniecenie/odkształcenie 1



Photo 78.

Kanapa tyl. - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 79.

Tapicerka drzwi przednich L - Inne 1



Photo 80.

Tapicerka drzwi przednich P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 81.

Tapicerka drzwi tylnych L - Wgniecenie/odkształcenie 1



Photo 82.

Wykładzina(y) słupka przedniego P - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 83.

Wykładzina podłogi bagażnika - Inne 1




Photo 84.

Wykładzina podłogi bagażnika - Inne 2