

DEKRA's commission No. : PKOL(W)/LODZ/101984/25/12/23
commission/ damage No. : 23/006622
Date of commission: 23-12-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0151623
Manufacturer	CUPRA
Model	Born 21-
Type / version	Born 58kWh E-Boost
Body type	hatchback
Number of doors / seats	5/5
Curb weight [kg]	1777
Gross vehicle weight [kg]	2280
Wheelbase 1/2	2766
Engine type	elektryczny
Pollution reduction system	-
Engine capacity [ccm]	0
Engine Power [hp/kW]	231/170
Gearbox	automatic
Registration /record No.	WP0013R
VIN / serial number	VSSZZZK11PP012472
Date of first registration	16-03-2023
Date of next. tech. test	16-03-2026
Year of manufacture	2022 (year has been verified with the manufacturer's base)
Readout [km]	71 066 (read)
Body color / type of coating	white/UNI

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	CONTINENTAL, WINTER CONTACT TS850 P	215/50 19 93T	3,0 mm
	left	CONTINENTAL, WINTER CONTACT TS850 P	215/50 19 93T	3,0 mm
back	right	CONTINENTAL, WINTER CONTACT TS850 P	215/50 19 93T	4,5 mm
	left	CONTINENTAL, WINTER CONTACT TS850 P	215/50 19 93T	4,5 mm

Standard equipment by Eurotax

- | | |
|---|---|
| 1. Active speed sign recognition, Adaptive Cruise Control | 38. LED Daytime running lights |
| 2. Android Auto, Apple CarPlay | 39. LED front dim light |
| 3. Antena dachowa w kształcie płetwy rekina | 40. LED rear lights, Side indicators |
| 4. Antilock-Brake-System (ABS) | 41. Lane control assistant |
| 5. Armrest (s) front | 42. Moulded sport seats |
| 6. Automated High-beam assist | 43. Multi functional steering wheel, Sports steering wheel, Steering wheel heated |
| 7. Automatic dimlight activation | 44. On board computer, On board monitor |
| 8. Bluetooth interface | 45. Other |
| 9. Bluetooth interface, Navigation system, Radio, Touchscreen monitor, USB in, Voice control for audiosystem, Voice control for navigation system | 46. Other |
| 10. Child seat fixation | 47. Other |
| 11. Colored glass | 48. Park Distance Control front, Park Distance Control rear |
| 12. DAB radio | 49. Podświetlenie podłokietnika w przednich drzwiach |
| 13. Distance control, Pedestrian Emergency Brake Assist | 50. Power windows front, Power windows rear |
| 14. Door mirror(s) electrically adjustable in general, Door mirrors electrically foldable | 51. Pre-Crash System |
| 15. Driver airbag, Head airbags front, Head airbags rear, Passenger airbag, Side airbag driver and passenger | 52. Radio, Touchscreen monitor, USB in, Voice control for audiosystem |
| 16. Driver conditioning monitoring | 53. Rain sensor |
| 17. Driver seat height adjustable, Passenger seat height adjustable | 54. Rear seat-backs foldable in two separate parts |
| 18. Dualzone automatic climate control | 55. Rear spoiler |
| 19. Electric tailgate, Remote controlled central locking | 56. Rear view camera |
| 20. Exterior design: other | 57. Rear-view mirror autodimming |
| 21. Exterior design: other | 58. Selectable driveline characteristics |
| 22. Exterior design: other | 59. Self sealing mobility tyre |
| 23. Exterior lighting: other | 60. Servotronic |
| 24. Exterior lighting: other | 61. Speed limiter |
| 25. Felgi aluminiowe 19 TYPHOON MACHINED SPORT BLACK / SILVER w kolorze czarnym | 62. System przypominający o konieczności zapinania pasów przy przednich i tylnych fotelach |
| 26. Floor mat | 63. Tapicerka materiałowa SEAQUAL wyprodukowana z materiałów recyklingowych, pozyskanych z mórz i ocean |
| 27. Fog lamps | 64. Textile upholstery |
| 28. Follow me home | 65. Traffic sign recognition |
| 29. Heated seat driver, Heated seat passenger | 66. Tyre pressure control (RDC) |
| 30. Interior lights: other accessories | 67. Uchwyt na napoje z przodu |
| 31. Interior lights: other accessories | 68. Uni-Lackierung |
| 32. Interior: other | 69. Vehicle charging cable |
| 33. Interior: other | 70. Wersja 5-miejscowa dla akumulatora 58 kWh |
| 34. Internet access, Telematic | 71. Wnętrze CUPRA z elementami dekoracyjnymi deski rozdzielczej w kolorze miedzi |
| 35. Internet access, Telematic | 72. Zderzaki CUPRA z elementami w kolorze miedzi |
| 36. Keyless Engine start, Keyless go | 73. Ładowarka 58kWh prądem stałym DC mocą 120kW |
| 37. Kieszenie w oparciach przednich foteli | |

Base value of the vehicle

Base value of the vehicle by Eurotax (gross) -

CorrectionsFirst registrationMileageTyresOther

Current market situation -

Uszkodzenia, stan. -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 01-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 20-01-2026

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Niesprawne przyciski funkcyjne w jednym z kluczyków, grot prawidłowy. Rysy na samochodzie. Pojazd elektryczny. Informacja: zalecane wykonanie przeglądu.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raporu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.

- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.
Próg lewy (widok od przodu)



Photo 12.
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.

Spód pojazdu przód



Photo 14.

Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika




Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdz.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Konsola środkowa



Photo 30.

Tunel środkowy

[illegible]

DEKRA Polska Sp. z o.o.
02-673 Warszawa, ul. Konstruktorska 12A
www.dekra.pl

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze



Photo 34.

Przewód ładowania baterii trakcyjnej

PHOTOGRAPHIC DOCUMENTATION



Photo 35.
Zdjęcie do protokołu



Photo 36.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 37.
Zdjęcie do protokołu



Photo 38.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zdjęcie do protokołu



Photo 42.

Atrapa przednia - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Listwa śr zderzaka przedniego - Pęknięcie/rozerwanie 1



Photo 44.

Zderzak - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Zderzak - Rysa/odprysk 2



Photo 46.

Drzwi przednie P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Felga aluminiowa tylna P - Rysa/odprysk 1



Photo 48.

Zderzak tylny - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Podłokietnik środkowy przedni - Inne 1



Photo 50.

Fotel prz. lew. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Fotel prz. praw. - Inne 1



Photo 52.

Wykładzina(y) słupka tylnego L - Rysa/odprysk 1