

DEKRA's commission No. : PKOL(W)/LODZ/76711/26/08/17
commission/ damage No. : 25/009788
Date of commission: 17-08-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
DEKRA Polska - współpraca O/Warszawa
mgr inż. Romuald Bocian (WSP)
DEKRA Polska - współpraca O/Puławy

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0127063
Manufacturer	MAZDA
Model	CX-5 17-21
Type / version	CX-5 2.5 Skypassion AWD aut
Body type	KOM
Number of doors / seats	5/5
Curb weight [kg]	1620
Gross vehicle weight [kg]	2140
Wheelbase 1/2	2700
Engine type	spark ignition
Pollution reduction system	three-way catalytic converter
Engine capacity [ccm]	2488
Engine Power [hp/kW]	194/143
Gearbox	automatic 6- gear
Registration /record No.	SK7F425
VIN / serial number	JMZKFGWMA00821097
Date of first registration	16-04-2019
Date of next. tech. test	05-06-2027
Year of manufacture	2019 (year has been verified with the manufacturer's base)
Readout [km]	200 801 (read)
Body color / type of coating	red/METALIK

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	BRIDGESTONE, TURANZA T005	225/55 19 99V	3,0 mm
	left	BRIDGESTONE, TURANZA T005	225/55 19 99V	3,0 mm
back	right	BRIDGESTONE, TURANZA T005	225/55 19 99V	3,0 mm
	left	BRIDGESTONE, TURANZA T005	225/55 19 99V	3,0 mm

Standard equipment by Eurotax

- | | |
|--|---|
| 1. 360 view camera | 38. LED rear lights |
| 2. Adaptive Cruise Control | 39. Lane control assistant |
| 3. Antilock-Brake-System (ABS) | 40. Lane control assistant, Rear view camera |
| 4. Armrest (s) front | 41. Lane control assistant, Rear view camera |
| 5. Armrest (s) rear | 42. Leather gearshifter/switch, Leather steering wheel |
| 6. Automatic climate control | 43. Leather upholstery |
| 7. Bluetooth interface | 44. Light Alloy wheels 19" |
| 8. Bord communication: other | 45. Luggage compartment cover |
| 9. Bord entertainment: other accessories | 46. Lumbar adjust driver electric |
| 10. Bord entertainment: other accessories | 47. Mobile Tire System |
| 11. Brake Assist | 48. Navigation system |
| 12. CD-player, Radio | 49. On board computer |
| 13. City Emergency Brake Assist | 50. On board monitor |
| 14. DAB radio | 51. Other |
| 15. Distribution of braking force electronically | 52. Park Distance Control front, Park Distance Control rear |
| 16. Door mirror(s) electrically adjustable in general, Door mirrors heated | 53. Power assisted brakes |
| 17. Door mirrors electrically foldable | 54. Power windows front, Power windows rear |
| 18. Driver airbag, Head airbags front, Head airbags rear, Passenger airbag, Side airbag driver and passenger | 55. Rain sensor |
| 19. Driver seat electrically adjustable, Memory seat, Passenger seat electrically adjustable | 56. Rear Cross Traffic Alert |
| 20. ESP (Electronical Stabilizing Program) | 57. Rear seat heating |
| 21. Electric parking brake | 58. Rear seat-backs foldable in two separate parts |
| 22. Electric tailgate | 59. Rear seat-backs foldable in two separate parts |
| 23. Exterior lighting: other | 60. Rear view camera |
| 24. Exterior lighting: other | 61. Rear-view mirror autodimming |
| 25. Fog lamps | 62. Remote controlled central locking |
| 26. Follow me home | 63. Soundsystem |
| 27. Full Cabin Spoiler | 64. Start/Stop system |
| 28. Head-Up Display | 65. Steering wheel heated |
| 29. Headlamp wash | 66. Tinted rear windows |
| 30. Heated seat driver, Heated seat passenger | 67. Traction control |
| 31. Hill holder | 68. Traffic sign recognition |
| 32. Interior lights: other accessories, Mirror: others | 69. Tyre pressure control (RDC) |
| 33. Interior: other | 70. USB in |
| 34. Keyless Engine start | 71. Vehicle immobilizer |
| 35. Keyless go | 72. Ventilated front seat |
| 36. LED Daytime running lights | 73. Windscreenwiper: other |
| 37. LED front dim light | |

Dealer's equipment (selected items)

1. Metallic paint -

Additional equipment

1. Hak holowniczy składany -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

CorrectionsFirst registrationMileageEquipmentTyresOther

Stan dbałości o pojazd, uszkodzenia i braki -
Grubość powłoki lakierowej -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 08-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 25-08-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
mgr inż. Romuald Bocian (WSP)

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	150 - 300
2	Left front fender	150 - 300
3	Left front pillar	150 - 300
4	Left front wall	150 - 300
5	Roof	150 - 300
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	150 - 300
9	Left side wall	150 - 300
10	Cover/tailgate	to 150
11	Side right wall	150 - 300
12	Rear right door	150 - 300
13	Middle right pillar	to 150
14	Front right door	150 - 300
15	Right side sill	to 150
16	Right front pillar	150 - 300
17	Right front fender	150 - 300

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:

bn

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:

.

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted (with the exception of the year of production) - adopted according to the documents presented and indicated sources.

Anti-theft protection

.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its

page 5/42

availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

1

Expert comments - regarding valuation

Brak półki bagażnika. Odpryski na szybie czołowej. Nie zwija się tylny prawy pas bezpieczeństwa. Podwyższona wartość grubości powłoki lakierowej wymaga dodatkowego sprawdzenia czy jest to powłoka fabryczna czy renowacyjna.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.
Próg lewy (widok od przodu)



Photo 12.
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód




Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Komora silnika

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Numer identyfikacyjny



Photo 22.
Tabliczka znamionowa

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Zestaw wskaźników - przebieg



Photo 24.

Zestaw wskaźników - serwis

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdź.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Konsola środkowa



Photo 30.


Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION**Photo 31.**


Kierownica (na wprost)

**Photo 32.**

Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Książka serwisowa – dane

**Photo 34.**

Książka serwisowa – ostatni przegląd

PHOTOGRAPHIC DOCUMENTATION



Photo 35.
Dow. Rej. Str. 2



Photo 36.
Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.
Zestaw naprawczy koła



Photo 38.
Kluczyki

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION




Photo 41.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 42.

Pokrywa komory silnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Felga aluminiowa przednia P - Rysa/odprysk 1



Photo 44.

Drzwi przednie P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Drzwi tylne P - Rysa/odprysk 1



Photo 46.

Drzwi tylne P - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Lusterko zew P - Rysa/odprysk 1




Photo 48.

Łotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 2



Photo 50.

Szyba tylna - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Zderzak tylny - Rysa/odprysk 1



Photo 52.

Zderzak tylny - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Dach - Rysa/odprysk 1



Photo 54.

Łotnik tylny L / Ściana boczna L - zdjęcie pogładowe 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1




Photo 56.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Drzwi przed L - Rysa/odprysk 1



Photo 58.

Drzwi tylne L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Drzwi tylne L - Rysa/odprysk 2




Photo 60.

Drzwi tylne L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Lusterko zew L - Rysa/odprysk 1



Photo 62.

Słupek przedni L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION




Photo 63.

Słupek środkowy L - Rysa/odprysk 1




Photo 64.

Słupek środkowy L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Felga Aluminiowa przednia L - Inne 1



Photo 66.

Koło kierownicy - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Tapicerka drzwi tylnych P - Pęknięcie/rozerwanie 1




Photo 68.

Podsufitka - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Listwy progowe praw. - Wgniecenie/odkształcenie 1



Photo 70.

Pas bezpieczeństwa tylny prawy - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 71.

Półka/roleta tylna - Inne 1