

DEKRA's commission No. : PKOL(W)/LODZ/64459/24/08/22
commission/ damage No. : 22/001226
Date of commission: 22-08-2024

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :
PKO Leasing Finance
PKO Leasing SA
Al. Śmigłego-Rydza 20
93-281 Łódź

Expert:
Marcin Sosnowski.
DEKRA Polska - Centrala
mgr Patryk Salzer
DEKRA Polska - współpraca O/Lębork

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0138721
Manufacturer	PORSCHE
Model	Cayenne III Coupe 19-23
Type / version	Cayenne Coupe
Body type	KOM
Number of doors / seats	5/4
Curb weight [kg]	2143
Gross vehicle weight [kg]	2795
Wheelbase 1/2	2895
Engine type	spark ignition
Pollution reduction system	GPF
Emission standard	EURO 6
Engine capacity [ccm]	2995
Engine Power [hp/kW]	340/250
Gearbox	automatic 8- gear
Registration /record No.	KR5XK41
VIN / serial number	WP1ZZZ9YZNDA41330
Date of first registration	24-01-2022
Date of next. tech. test	24-01-2025
Year of manufacture	2021 (year has been verified with the manufacturer's base)
Readout [km]	65 182 (read)
Body color / type of coating	white/plain

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	PIRELLI, P ZERO	315/30 22 107Y	5,0 mm
	left	PIRELLI, P ZERO	315/30 22 107Y	5,0 mm
back	right	PIRELLI, P ZERO	285/35 22 106Y	4,0 mm
	left	PIRELLI, P ZERO	285/35 22 106Y	4,0 mm

Standard equipment by Eurotax

- | | |
|--|--|
| 1. Active body control | 42. Interior: other |
| 2. Active body control | 43. Keyless Engine start |
| 3. Additional gauges | 44. LED Daytime running lights |
| 4. Alarm | 45. LED front dim light |
| 5. Antilock-Brake-System (ABS) | 46. LED rear lights |
| 6. Apple CarPlay, Bord communication: other, Internet access | 47. Light Alloy wheels 20'' |
| 7. Armrest (s) rear | 48. Metal finish |
| 8. Automated High-beam assist, Follow me home | 49. Mirror: others |
| 9. Automatic limited slip differential | 50. Multi functional steering wheel, Steering wheel with gear-switches |
| 10. Bord communication: other | 51. On board monitor |
| 11. CD-player, DVD-player, Navigation system, On board monitor, Radio | 52. Other |
| 12. Cabin air filter | 53. Other |
| 13. Child seat(s) | 54. Other |
| 14. Collision Warning System, Pedestrian Emergency Brake Assist, Power assisted brakes | 55. Other |
| 15. Cruise control | 56. Other |
| 16. DAB radio, Radio | 57. Other |
| 17. Distance control | 58. Park Assistant, Park Distance Control front, Park Distance Control rear, Rear view camera |
| 18. Door mirror(s) electrically adjustable in general, Door mirrors electrically foldable, Door mirrors heated, Exterior lighting: other, Mirror: others | 59. Power steering |
| 19. Driver airbag, Head airbags front, Head airbags rear, Passenger airbag, Side airbag driver, Side airbag driver and passenger | 60. Pre-Crash System |
| 20. Driver knee airbag, Passenger knee airbag | 61. Rain sensor |
| 21. Driver seat electrically adjustable, Passenger seat electrically adjustable, Sport seats front | 62. Rear window heating |
| 22. Dualzone automatic climate control | 63. Remote controlled central locking |
| 23. ESP (Electronical Stabilizing Program) | 64. Rev counter |
| 24. Electric tailgate | 65. Roll over protection system |
| 25. Electric tailgate, Rear spoiler | 66. Seatbelt pretensioner front, Seatbelt pretensioner rear, Seatbelts vertically adjustable front, Seatbelts vertically adjustable rear |
| 26. Energy recovery system | 67. Selectable driveline characteristics |
| 27. Engine Brake | 68. Side Pre-Crash System |
| 28. Engine: other | 69. Soundsystem |
| 29. Exterior design: other | 70. Start/Stop system |
| 30. Exterior design: other | 71. Steering wheel electrically adjustable |
| 31. Exterior design: other | 72. Storage facilities in general |
| 32. Exterior design: other | 73. Third braking light |
| 33. Exterior design: other | 74. Towbar preparation |
| 34. Exterior design: other, Exterior lighting: other | 75. Traction control |
| 35. Exterior lighting: other | 76. Transport/loading: other |
| 36. Extra power outlet, USB in | 77. Tyre pressure control (RDC) |
| 37. Full Cabin Spoiler | 78. Uni-Lackierung |
| 38. Hill descent control | 79. Upholstery with leather inserts |
| 39. Hill holder | 80. Vehicle immobilizer |
| 40. Interior decoration: other | 81. {System stabilizacji ciągnionej przyczepy} |
| 41. Interior lights: other accessories | |

Dealer's equipment (selected items)

1. Adaptive Cruise Control	-
2. Automatic climate control	-
3. Comfort driver seat, Comfort passenger seat, Driver seat electrically adjustable, Memory seat, Passenger seat electrically adjustable	-
4. Door mirrors autodimming, Rear-view mirror autodimming	-
5. Exterior design: other	-
6. Floor mat	-
7. Gearshifter/switch in metal	-
8. Heated seat driver, Heated seat passenger, Rear seat heating	-
9. Interior decoration: other	-
10. Interior lights: other accessories	-
11. LED front dim light	-
12. Leather upholstery	-
13. Light alloy wheels 22"	-
14. Park Assistant, Park Distance Control front, Park Distance Control rear, Rear view camera	-
15. Tinted rear windows	-
16. Ventilated front seat	-

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

Stwierdzone braki/uszkodzenia -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 08-2024 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 29-08-2024

DEKRA's expert:
Marcin Sosnowski.
mgr Patryk Salzer

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Left front fender	to 150
3	Left front pillar	to 150
4	Left front wall	to 150
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	to 150
9	Left side wall	to 150
10	Cover/tailgate	to 150
11	Side right wall	to 150
12	Rear right door	to 150
13	Middle right pillar	to 150
14	Front right door	to 150
15	Right side sill	to 150
16	Right front pillar	to 150
17	Right front fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:

.

Information concerning the origin of the vehicle

Lack of reliable data.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia parkingowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

fabryczne

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

2

Expert comments - regarding valuation

Brak możliwości dokładnej oceny stanu technicznego i powłoki lakierniczej.

Przedmiotowa ocena została wykonana organoleptycznie bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego.

Nie dokonywano demontażu osłon i innych.

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego.

Restrictive disclaimer - regarding valuation

- Specyfikacja wg programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym, w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

- Niniejsza wycena nie jest ofertą handlową.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Komora silnika

PHOTOGRAPHIC DOCUMENTATION




Photo 21.
Numer identyfikacyjny



Photo 22.
Tabliczka znamionowa

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Zestaw wskaźników - przebieg



Photo 24.

Widok przez otwarte drzwi przednie lewe

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Kierownica z lewej strony



Photo 26.

Widok przez otwarte drzwi tylne lewe

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok z tylnej kanapy na deskę rozd.



Photo 28.

Konsola środkowa

PHOTOGRAPHIC DOCUMENTATION




Photo 29.
Tunel środkowy




Photo 30.
Kierownica (na wprost)

PHOTOGRAPHIC DOCUMENTATION**Photo 31.**

Dowód rej. Str. 1

**Photo 32.**

Dow. Rej. Str.2 i klucze

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Książka serwisowa – dane

**Photo 34.**

Książka serwisowa – ostatni przegląd

PHOTOGRAPHIC DOCUMENTATION



Photo 35.
Instrukcje



Photo 36.
Pokrywa komory silnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zderzak - Rysa/odprysk 1



Photo 38.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Felga aluminiowa przednia P - Rysa/odprysk 2



Photo 40.

Zderzak tylny - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Błotnik przedni L - Rysa/odprysk 1



Photo 42.

Felga Aluminiowa przednia L - Rysa/odprysk 1