

DEKRA's commission No. : PKOL(W)/LODZ/86261/26/09/14  
commission/ damage No. : 21/057542  
Date of commission: 14-09-2026

**DEKRA Poland - Headquarters**  
02-673 Warszawa, ul. Konstruktorska 12A

**Client :**

PKO Leasing SA  
Świętokrzyska 36  
00-116 Warszawa

**Expert:**

**Kacper Sosnowski (WSP)**  
DEKRA Polska - współpraca O/Warszawa  
**inż. Józef Orłowski**  
TU - Włocławek

**NOTE:**

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

**Vehicle data**

|                              |                                                            |
|------------------------------|------------------------------------------------------------|
| Group of objects (Eurotax)   | jeeps                                                      |
| EC code (Eurotax)            | 0144991                                                    |
| Manufacturer                 | KIA                                                        |
| Model                        | Sorento 20-24                                              |
| Type / version               | Sorento 2.2 CRDi XL 4WD DCT 7os.                           |
| Body type                    | KOM                                                        |
| Number of doors / seats      | 5/7                                                        |
| Curb weight [kg]             | 1819                                                       |
| Gross vehicle weight [kg]    | 2600                                                       |
| Wheelbase 1/2                | 2815                                                       |
| Engine type                  | Automatic ignition                                         |
| Pollution reduction system   | KSC                                                        |
| Engine capacity [ccm]        | 2151                                                       |
| Engine Power [hp/kW]         | 202/148                                                    |
| Gearbox                      | automatic 8- gear                                          |
| Registration /record No.     | GD1A493                                                    |
| VIN / serial number          | KNARH81BHN5128670                                          |
| Date of first registration   | 16-12-2021                                                 |
| Date of next. tech. test     | 16-12-2026                                                 |
| Year of manufacture          | 2021 (year has been verified with the manufacturer's base) |
| Readout [km]                 | 105 450 (read)                                             |
| Body color / type of coating | gray/METALIK                                               |

**Tyres**

| axle  | Wheel | Manufacturer, type             | Size           | Measured profile |
|-------|-------|--------------------------------|----------------|------------------|
| Front | right | CONTINENTAL, PREMIUM CONTACT 6 | 255/45 20 105V | 1,0 mm           |
|       | left  | CONTINENTAL, PREMIUM CONTACT 6 | 255/45 20 105V | 1,0 mm           |
| back  | right | CONTINENTAL, PREMIUM CONTACT 6 | 255/45 20 105V | 3,5 mm           |
|       | left  | CONTINENTAL, PREMIUM CONTACT 6 | 255/45 20 105V | 3,5 mm           |

Standard equipment by Eurotax

- |                                                                                                            |                                                                        |
|------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------|
| 1. 2 single seats rear                                                                                     | 50. Other                                                              |
| 2. Accoustic windows                                                                                       | 51. Other                                                              |
| 3. Active Emergency Brake Assist                                                                           | 52. Other                                                              |
| 4. Active Emergency Brake Assist                                                                           | 53. Other                                                              |
| 5. Adaptive Cruise Control                                                                                 | 54. Other                                                              |
| 6. Airbag: other                                                                                           | 55. Other                                                              |
| 7. Alarm                                                                                                   | 56. Other                                                              |
| 8. Antilock-Brake-System (ABS)                                                                             | 57. Other                                                              |
| 9. Armrest (s) front, Armrest (s) rear, Storage facilities in general                                      | 58. Other                                                              |
| 10. Automated High-beam assist                                                                             | 59. Other                                                              |
| 11. Automatic Emergency Call                                                                               | 60. Other                                                              |
| 12. Automatic climate control                                                                              | 61. Other                                                              |
| 13. Automatic dimlight activation                                                                          | 62. Other                                                              |
| 14. Bluetooth interface, Bord communication: other, Hands-free system, Navigation system, On board monitor | 63. Other                                                              |
| 15. Bluetooth interface, Multi functional steering wheel, Steering wheel with radio operation              | 64. Park Distance Control front, Park Distance Control rear            |
| 16. Child seat fixation                                                                                    | 65. Passenger seat electrically adjustable                             |
| 17. Digital instruments                                                                                    | 66. Power assisted brakes                                              |
| 18. Diminished spare wheel                                                                                 | 67. Power windows front, Power windows rear                            |
| 19. Distance control, Lane control assistant, Traffic jam assist                                           | 68. Power windows front, Power windows rear                            |
| 20. Door mirror(s) electrically adjustable in general                                                      | 69. Rain sensor                                                        |
| 21. Door mirrors electrically foldable                                                                     | 70. Rear Cross Traffic Alert                                           |
| 22. Door mirrors heated                                                                                    | 71. Rear Cross Traffic Alert                                           |
| 23. Driver airbag, Passenger airbag                                                                        | 72. Rear seat heating                                                  |
| 24. Driver seat electrically adjustable, Lumbar adjust driver electric                                     | 73. Rear seat-backs foldable in two separate parts                     |
| 25. ESP (Electronical Stabilizing Program)                                                                 | 74. Rear seat-backs foldable in two separate parts                     |
| 26. Electric parking brake                                                                                 | 75. Rear view camera                                                   |
| 27. Electric tailgate                                                                                      | 76. Rear-view mirror autodimming                                       |
| 28. Exterior design: other                                                                                 | 77. Remote controlled central locking                                  |
| 29. Exterior design: other, Side indicators                                                                | 78. Roof railing                                                       |
| 30. Fog lamps                                                                                              | 79. Seatbelt pretensioner front, Seatbelts vertically adjustable front |
| 31. Full Cabin Spoiler                                                                                     | 80. Seatbelt pretensioner front, Seatbelts vertically adjustable front |
| 32. Head airbags front, Head airbags rear, Side airbag driver and passenger                                | 81. Selectable driveline characteristics                               |
| 33. Headrest rear, middle, Headrests front, Rear headrests                                                 | 82. Start/Stop system                                                  |
| 34. Heated seat driver, Heated seat passenger                                                              | 83. Steering wheel heated                                              |
| 35. Hill descent control                                                                                   | 84. Steering wheel manually adjustable                                 |
| 36. Hill holder                                                                                            | 85. Steering wheel with gear-switches                                  |
| 37. Interior decoration: other                                                                             | 86. Storage facilities in general                                      |
| 38. Interior lights: other accessories                                                                     | 87. Storage facilities in general                                      |
| 39. Interior lights: other accessories                                                                     | 88. Sunblind rear side door manual                                     |
| 40. Keyless go, Other                                                                                      | 89. Tinted rear windows                                                |
| 41. LED Daytime running lights                                                                             | 90. Traffic sign recognition                                           |
| 42. LED front dim light                                                                                    | 91. Tyre pressure control (RDC)                                        |
| 43. LED rear lights                                                                                        | 92. USB in                                                             |
| 44. Lane control assistant                                                                                 | 93. USB in                                                             |
| 45. Lane control assistant                                                                                 | 94. Uni-Lackierung                                                     |
| 46. Leather steering wheel                                                                                 | 95. Vehicle immobilizer                                                |
| 47. Leather upholstery                                                                                     | 96. Windows: other                                                     |
| 48. Light Alloy wheels 19"                                                                                 | 97. mp3 Player, Radio, Soundsystem, USB in                             |

49. Luggage compartment cover

98. {TSA - system stabilizacji toru jazdy przyczepy}

Dealer's equipment (selected items)

1. Metallic paint ..... -

**Base value of the vehicle**

Base value of the vehicle by Eurotax (net) ..... -

**Corrections**First registrationMileageEquipmentTyresOther

stwierdzone braki i uszkodzenia ..... -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 09-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 28-09-2026

DEKRA's expert:  
Kacper Sosnowski (WSP)  
inż. Józef Orłowski

**Document issued electronically valid without signature.**

Measurement of thickness of the vehicle lacquer coating


| No. of controlled item | Controlled item     | Measured range of thickness of the lacquer coat [μm] |
|------------------------|---------------------|------------------------------------------------------|
| 1                      | Front cover         | to 150                                               |
| 2                      | Left front fender   | to 150                                               |
| 3                      | Left front pillar   | to 150                                               |
| 4                      | Left front wall     | to 150                                               |
| 5                      | Roof                | to 150                                               |
| 6                      | Left middle pillar  | to 150                                               |
| 7                      | Left side sill      | to 150                                               |
| 8                      | Left rear wall      | to 150                                               |
| 9                      | Left side wall      | to 150                                               |
| 10                     | Cover/tailgate      | to 150                                               |
| 11                     | Side right wall     | to 150                                               |
| 12                     | Rear right door     | to 150                                               |
| 13                     | Middle right pillar | to 150                                               |
| 14                     | Front right door    | to 150                                               |
| 15                     | Right side sill     | to 150                                               |
| 16                     | Right front pillar  | to 150                                               |
| 17                     | Right front fender  | to 150                                               |

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book of the vehicle was not provided.

**Information concerning the origin of the vehicle**

The vehicle purchased domestically from an authorized representative of the brand.

**Additional comments on the car:**

Not applicable.

**Test drive**

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below: ograniczenia parkingowe

**Checking of the correctness and / or construction of identification / serial numbers of the object:**

Not tested

**Verification of the accuracy of the object data, including year of production, and other.**

Not conducted - adopted according to the documents presented and indicated sources.

**Anti-theft protection**

alarm immobilizer

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

**Kluczyki**

TAK

1

---

Expert comments - regarding valuation

Brak półki bagażnika. Rysy na samochodzie. Opony przednie mocno zużyte. Odpryski na szybie czołowej.

PHOTOGRAPHIC DOCUMENTATION



**Photo 1.**  
Przekątna przednia lewa



**Photo 2.**  
Przód

PHOTOGRAPHIC DOCUMENTATION



**Photo 3.**

Przekątna przednia prawa



**Photo 4.**

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



**Photo 5.**  
Bok prawy z tyłu



**Photo 6.**  
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



**Photo 7.**

Tył



**Photo 8.**

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



**Photo 9.**

Bok lewy z tyłu



**Photo 10.**

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



**Photo 11.**  
Próg lewy (widok od przodu)



**Photo 12.**  
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION




**Photo 13.**  
Spód pojazdu przód



**Photo 14.**  
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



**Photo 15.**

Tarcza hamulcowa przednia prawa



**Photo 16.**

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



**Photo 17.**

Tarcza hamulcowa tylna lewa



**Photo 18.**

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



**Photo 19.**  
Bagażnik



**Photo 20.**  
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



**Photo 21.**  
Komora silnika



**Photo 22.**  
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



**Photo 23.**

Tabliczka znamionowa



**Photo 24.**

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



**Photo 25.**

Zestaw wskaźników - serwis



**Photo 26.**

Widok przez otwarte drzwi przednie lewe

PHOTOGRAPHIC DOCUMENTATION



**Photo 27.**

Kierownica z lewej strony



**Photo 28.**

Widok przez otwarte drzwi tylne lewe

PHOTOGRAPHIC DOCUMENTATION



**Photo 29.**

Widok z tylnej kanapy na deskę rozd.



**Photo 30.**

Konsola środkowa

PHOTOGRAPHIC DOCUMENTATION



**Photo 31.**  
Tunel środkowy



**Photo 32.**  
Kierownica (na wprost)

[illegible]

The image displays an open Polish passport. On the left side, there are several official stamps and handwritten notes:

- A red circular stamp at the top left reads "WYDZIAŁ PASZPORTOWY I WIZOWY URZĘDU MIGRACJI POLSKIEJ W Białymostku".
- Below it is a rectangular stamp dated "16.12.2024".
- Handwritten in blue ink across the middle is "2026.12.16".
- Another handwritten date "2024.12.16" is written below the first one.
- There are two green rectangular stamps, each labeled "WYSTAWIŁ" (Issued).
- At the bottom left, there is a small black rectangular stamp with a white eagle emblem.

The right side of the passport features a large yellow area with a geometric pattern, intended for visas. At the bottom of this area, there is a small black rectangular stamp with a white eagle emblem. Below the yellow area, there is a small black rectangular stamp with a white eagle emblem.

**DEKRA Polska Sp. z o.o.**  
02-673 Warszawa, ul. Konstruktorska 12A  
[www.dekra.pl](http://www.dekra.pl)

PHOTOGRAPHIC DOCUMENTATION



**Photo 35.**

Kluczyki



**Photo 36.**

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 37.**

Zdjęcie do protokołu



**Photo 38.**

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 39.**

Zdjęcie do protokołu



**Photo 40.**


Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 41.**

Zdjęcie do protokołu



**Photo 42.**

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 43.**

Kratka/zaślepka halogenu L - zdjęcie poglądowe 1



**Photo 44.**


Kratka/zaślepka halogenu L - Inne 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 45.**

Pokrywa komory silnika - zdjęcie poglądowe 1



**Photo 46.**

Pokrywa komory silnika - Inne 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 47.**

Zderzak przedni cz górna - Rysa/odprysk 1



**Photo 48.**

Światnik przedni P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 49.**

Felga aluminiowa przednia P - Rysa/odprysk 1



**Photo 50.**

Listwa krawędzi błotnika prz P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 51.**

Opona przednia P - Pęknięcie/rozerwanie 1



**Photo 52.**

Drzwi przednie P - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 53.**

Drzwi przednie P - Rysa/odprysk 1



**Photo 54.**

Drzwi przednie P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 55.**

Drzwi tylne P - Rysa/odprysk 1



**Photo 56.**

Drzwi tylne P - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



**Photo 57.**

Drzwi tylne P - Wgniecenie/odkształcenie 1



**Photo 58.**

Ściana boczna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 59.**

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1



**Photo 60.**

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



**Photo 61.**

Listwa śr zderzaka tylnego - Rysa/odprysk 1



**Photo 62.**

Listwa śr zderzaka tylnego - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



**Photo 63.**

Pokrywy bagażnika - Rysa/odprysk 1



**Photo 64.**

Zderzak tylny - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 65.**

Zderzak tylny - Rysa/odprysk 2



**Photo 66.**

Zderzak tylny cz dolna - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 67.**

Błotnik tylny L / Ściana boczna L - Rysa/odprysk 1



**Photo 68.**


Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 69.**


Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 2



**Photo 70.**

Błotnik tylny L / Ściana boczna L() - Wgniecenie/odkształcenie 3

PHOTOGRAPHIC DOCUMENTATION



**Photo 71.**

Felga aluminiowa tylna L - Rysa/odprysk 1



**Photo 72.**


Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 73.**

Drzwi przed L - Wgniecenie/odkształcenie 1



**Photo 74.**


Drzwi tylne L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 75.**

Drzwi tylne L - Wgniecenie/odkształcenie 1



**Photo 76.**

Lusterko zew L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 77.**  
Próg L - Rysa/odprysk 1



**Photo 78.**  
Felga Aluminiowa przednia L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 79.**

Koło kierownicy - Rysa/odprysk 1



**Photo 80.**

Fotel prz. praw. - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 81.**

Fotel prz. praw. - Rysa/odprysk 2



**Photo 82.**

Tapicerka drzwi tylnych L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 83.**

Tapicerka drzwi tylnych P - Rysa/odprysk 1



**Photo 84.**

Tapicerka drzwi tylnych P - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 85.**

Uchwyt drzwi tyl L - Pęknięcie/rozerwanie 1



**Photo 86.**

Osłona p/słoneczna prawa - Inne 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 87.**

Listwy progowe lew. - Wgniecenie/odkształcenie 1



**Photo 88.**


Listwy progowe praw. - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 89.**

Wykładzina podłogi - Inne 1



**Photo 90.**

Półka/roleta tylna - Inne 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 91.**

Wykładzina podłogi bagażnika - Inne 1



**Photo 92.**

Wykładzina pokrywy tylnej - Rysa/odprysk 1