

DEKRA's commission No. : PKOL(W)/LODZ/76868/26/08/18  
commission/ damage No. : PS25/00062  
Date of commission: 18-08-2026

**DEKRA Poland - Headquarters**  
02-673 Warszawa, ul. Konstruktorska 12A

**Client :**

PKO Leasing SA  
Świętokrzyska 36  
00-116 Warszawa

**Expert:**

**Kacper Sosnowski (WSP)**  
DEKRA Polska - współpraca O/Warszawa  
**Ivan Halaburda (WSP)**  
DEKRA Polska - współpraca O/Białystok

**NOTE:**

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

**Vehicle data**

|                              |                                                            |
|------------------------------|------------------------------------------------------------|
| Group of objects (Eurotax)   | cars                                                       |
| EC code (Eurotax)            | 0149530                                                    |
| Manufacturer                 | FORD                                                       |
| Model                        | Mustang Fastback 18-24                                     |
| Type / version               | Mustang 5.0 V8 Mach 1 aut                                  |
| Body type                    | CPE                                                        |
| Number of doors / seats      | 3/4                                                        |
| Curb weight [kg]             | 1861                                                       |
| Gross vehicle weight [kg]    | 2150                                                       |
| Wheelbase 1/2                | 2720                                                       |
| Engine type                  | spark ignition                                             |
| Pollution reduction system   | GPF                                                        |
| Engine capacity [ccm]        | 5038                                                       |
| Engine Power [hp/kW]         | 460/338                                                    |
| Gearbox                      | automatic 10- gear                                         |
| Registration /record No.     | V8MACH1                                                    |
| VIN / serial number          | 1FA6P8R09N5554726                                          |
| Date of first registration   | 17-01-2025                                                 |
| Date of next. tech. test     | 25-06-2027                                                 |
| Year of manufacture          | 2022 (year has been verified with the manufacturer's base) |
| Readout [km]                 | 38 343 (read)                                              |
| Body color / type of coating | blue/METALIK                                               |

Tyres

| axle  | Wheel | Manufacturer, type       | Size           | Measured profile |
|-------|-------|--------------------------|----------------|------------------|
| Front | right | MICHELIN, PILOT SPORT 4S | 255/40 19 100Y | 5,0 mm           |
|       | left  | MICHELIN, PILOT SPORT 4S | 255/40 19 100Y | 5,0 mm           |
| back  | right | MICHELIN, PILOT SPORT 4S | 275/40 19 105Y | 2,0 mm           |
|       | left  | MICHELIN, PILOT SPORT 4S | 275/40 19 105Y | 2,0 mm           |

Standard equipment by Eurotax

- |                                                                                                                                                                                                                                                                                                 |                                                    |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------|
| 1. Active body control                                                                                                                                                                                                                                                                          | 39. Interior: other, Storage facilities in general |
| 2. Alarm                                                                                                                                                                                                                                                                                        | 40. Internet access, Keyless entry, Other          |
| 3. Android Auto, Apple CarPlay, Bluetooth interface, CD-player, DAB radio, Hands-free system, mp3 Player, Navigation system, On board monitor, Radio, Soundsystem, Touchscreen monitor, USB in, Voice control for audiosystem, Voice control for navigation system, Voice control for telephone | 41. Keyless go                                     |
| 4. Antilock-Brake-System (ABS)                                                                                                                                                                                                                                                                  | 42. Keyless go, Remote controlled central locking  |
| 5. Automated High-beam assist, Automatic dimlight activation                                                                                                                                                                                                                                    | 43. LED Daytime running lights                     |
| 6. Automatic dimlight activation                                                                                                                                                                                                                                                                | 44. LED front dim light                            |
| 7. Brake Assist, Collision Warning System, Pedestrian Emergency Brake Assist, Pre-Crash System                                                                                                                                                                                                  | 45. LED rear lights                                |
| 8. Bumpers: other, Exterior design: other                                                                                                                                                                                                                                                       | 46. Lane control assistant                         |
| 9. Bumpers: other, Exterior design: other                                                                                                                                                                                                                                                       | 47. Leather steering wheel, Steering wheel heated  |
| 10. Bumpers: other, Exterior design: other                                                                                                                                                                                                                                                      | 48. Light Alloy wheels 19"                         |
| 11. Child seat fixation                                                                                                                                                                                                                                                                         | 49. Mobile Tire System                             |
| 12. Cruise control                                                                                                                                                                                                                                                                              | 50. Multi functional steering wheel                |
| 13. Digital instruments, On board monitor                                                                                                                                                                                                                                                       | 51. Other                                          |
| 14. Distribution of braking force electronically                                                                                                                                                                                                                                                | 52. Other                                          |
| 15. Door mirror(s) electrically adjustable in general, Door mirrors electrically foldable, Door mirrors heated, Exterior lighting: other                                                                                                                                                        | 53. Other                                          |
| 16. Driver airbag, Passenger airbag                                                                                                                                                                                                                                                             | 54. Other                                          |
| 17. Driver knee airbag                                                                                                                                                                                                                                                                          | 55. Other                                          |
| 18. Driver seat electrically adjustable                                                                                                                                                                                                                                                         | 56. Other                                          |
| 19. Driver-information-system, Other                                                                                                                                                                                                                                                            | 57. Passenger seat electrically adjustable         |
| 20. Dualzone automatic climate control                                                                                                                                                                                                                                                          | 58. Power steering                                 |
| 21. ESP (Electronical Stabilizing Program), Power assisted brakes, Traction control                                                                                                                                                                                                             | 59. Power windows front                            |
| 22. Exterior design: other                                                                                                                                                                                                                                                                      | 60. Rear bench foldable in two separate parts      |
| 23. Exterior design: other                                                                                                                                                                                                                                                                      | 61. Rear spoiler                                   |
| 24. Exterior design: other                                                                                                                                                                                                                                                                      | 62. Rear view camera                               |
| 25. Exterior design: other                                                                                                                                                                                                                                                                      | 63. Rear-view mirror autodimming                   |
| 26. Exterior design: other                                                                                                                                                                                                                                                                      | 64. Remote controlled central locking              |
| 27. Exterior design: other                                                                                                                                                                                                                                                                      | 65. Selectable driveline characteristics           |
| 28. Exterior design: other                                                                                                                                                                                                                                                                      | 66. Side airbag driver and passenger               |
| 29. Floor mat                                                                                                                                                                                                                                                                                   | 67. Side indicators                                |
| 30. Fog lamps                                                                                                                                                                                                                                                                                   | 68. Sport seats front                              |
| 31. Head airbags front, Head airbags rear                                                                                                                                                                                                                                                       | 69. Steering wheel with gear-switches              |
| 32. Heated seat driver, Heated seat passenger, Ventilated front seat                                                                                                                                                                                                                            | 70. Tyre pressure control (RDC)                    |
| 33. Hill holder                                                                                                                                                                                                                                                                                 | 71. Uni-Lackierung                                 |
| 34. Interior lights: other accessories                                                                                                                                                                                                                                                          | 72. Upholstery with leather inserts                |
| 35. Interior: other                                                                                                                                                                                                                                                                             | 73. Vehicle immobilizer                            |
| 36. Interior: other                                                                                                                                                                                                                                                                             | 74. Wheels: other                                  |
| 37. Interior: other                                                                                                                                                                                                                                                                             | 75. Windows: other                                 |
| 38. Interior: other                                                                                                                                                                                                                                                                             | 76. Windscreenwiper: other                         |

Dealer's equipment (selected items)

- |                           |       |   |
|---------------------------|-------|---|
| 1. Light Alloy wheels 19" | ..... | - |
| 2. Metallic paint         | ..... | - |

**Base value of the vehicle**

Base value of the vehicle by Eurotax (net) ..... -

**Corrections**First registrationMileageEquipmentTyresOther

State of the vehicle ..... -

Earlier repairs ..... -

Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 08-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 21-08-2026

DEKRA's expert:  
Kacper Sosnowski (WSP)  
Ivan Halaburda (WSP)**Document issued electronically valid without signature.**

Measurement of thickness of the vehicle lacquer coating


| No. of controlled item | Controlled item     | Measured range of thickness of the lacquer coat [ $\mu\text{m}$ ] |
|------------------------|---------------------|-------------------------------------------------------------------|
| 1                      | Front cover         | 150 - 200                                                         |
| 2                      | Front left fender   | 150 - 300                                                         |
| 3                      | Left front pillar   | to 150                                                            |
| 4                      | Front left door     | to 150                                                            |
| 5                      | Roof                | to 150                                                            |
| 6                      | Left middle pillar  | to 150                                                            |
| 7                      | Right side sill     | to 150                                                            |
| 9                      | Rear left fender    | to 150                                                            |
| 10                     | Cover/lid           | to 150                                                            |
| 11                     | Right rear fender   | 150 - 200                                                         |
| 13                     | Right middle pillar | to 150                                                            |
| 14                     | Right side sill     | to 150                                                            |
| 15                     | Front right door    | 150 - 300                                                         |
| 16                     | Right front pillar  | to 150                                                            |
| 17                     | Front right fender  | 150 - 300                                                         |

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book of the vehicle was not provided.

**Information concerning the origin of the vehicle**

The vehicle purchased domestically from an authorized representative of the brand.

**Anti-theft protection - immobilizer**

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

**Anti-theft protection - other:**

not found

**Additional comments on the car:**

Not applicable.

**Test drive**

The test drive has been conducted on a distance and in time enabling rough estimation of the technical condition of the vehicle.

**Checking of the correctness and / or construction of identification / serial numbers of the object:**

Not tested

**Verification of the accuracy of the object data, including year of production, and other.**

Not conducted (with the exception of the year of production) - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

---

#### Comments to the commission - regarding valuation

##### **Kluczyki**

TAK

2

---

#### Expert comments - regarding valuation

Rysy na samochodzie. Nieprzyjemny zapach w samochodzie. Widoczne wady lakiernicze. Nieprawny akumulator. Odpryski na szybie czołowej.

#### Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



**Photo 1.**  
Przekątna przednia lewa



**Photo 2.**  
Przód

PHOTOGRAPHIC DOCUMENTATION



**Photo 3.**

Przekątna przednia prawa



**Photo 4.**

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



**Photo 5.**  
Bok prawy z tyłu



**Photo 6.**  
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



**Photo 7.**

Tył



**Photo 8.**

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



**Photo 9.**

Bok lewy z tyłu



**Photo 10.**

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



**Photo 11.**  
Próg lewy (widok od przodu)



**Photo 12.**  
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



**Photo 13.**  
Spód pojazdu przód



**Photo 14.**  
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



**Photo 15.**

Tarcza hamulcowa przednia prawa



**Photo 16.**

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



**Photo 17.**

Tarcza hamulcowa tylna lewa



**Photo 18.**

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



**Photo 19.**  
Bagażnik



**Photo 20.**  
Komora silnika

PHOTOGRAPHIC DOCUMENTATION



**Photo 21.**  
Numer identyfikacyjny



**Photo 22.**  
Tabliczka znamionowa

PHOTOGRAPHIC DOCUMENTATION



**Photo 23.**

Zestaw wskaźników - przebieg



**Photo 24.**

Zestaw wskaźników - serwis

PHOTOGRAPHIC DOCUMENTATION



**Photo 25.**

Widok przez otwarte drzwi przednie lewe



**Photo 26.**

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



**Photo 27.**

Widok przez otwarte drzwi tylne lewe



**Photo 28.**

Widok z tylnej kanapy na deskę rozdziel.

PHOTOGRAPHIC DOCUMENTATION



**Photo 29.**  
Konsola środkowa



**Photo 30.**  
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION

**Photo 31.**  
Kierownica (na wprost)



**Photo 32.**  
Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 33.**  
Dow. Rej. Str. 2



**Photo 34.**  
Instrukcje

PHOTOGRAPHIC DOCUMENTATION



**Photo 35.**  
Zestaw naprawczy koła



**Photo 36.**  
Kluczyki

PHOTOGRAPHIC DOCUMENTATION



**Photo 37.**  
Zdjęcie do protokołu



**Photo 38.**  
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 39.**

Zdjęcie do protokołu



**Photo 40.**

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 41.**

Spoiler zderzaka przedniego - Rysa/odprysk 1



**Photo 42.**

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 43.**

Drzwi przednie P - Wgniecenie/odkształcenie 1



**Photo 44.**

Lusterko zew P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 45.**

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1



**Photo 46.**


Felga aluminiowa tylna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 47.**

Dach - zdjęcie poglądowe 1



**Photo 48.**

Dach - Inne 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 49.**

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1



**Photo 50.**

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 51.**

Słupki przedni L - zdjęcie poglądowe 1



**Photo 52.**

Słupki przedni L - Inne 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 53.**

Felga Aluminiowa przednia L - Rysa/odprysk 1



**Photo 54.**

Opona przednia L - Pęknięcie/rozerwanie 1